

Installer: SmartSun

Customer: Leigh Matthews

Subject: PV System Post Construction Inspection

Date: 7/7/2023

To whom it may concern:

Model Energy, PLLC performed a field inspection on June 29, 2023, to the property located at 620 Harvell Rd, Coats, NC 27521 and has reviewed the installation details of the ground mount PV system that was installed by SmartSun. The field inspection was performed by myself, Andrew King (a North Carolina registered design professional), or a person under my direct supervisory control. The review was limited to the structural elements involved in the construction.

The structural installation of the PV system was inspected and is in compliance with the 2018 North Carolina Residential Building Code. In addition, the PV system was installed in accordance with the structural documents submitted for permitting and was installed using standard and sound construction practices.

Thank you,

Andrew King, PE

