

Installer: SmartSun

Customer: Stump, Richard

Subject: PV System Post Construction Inspection

Date: 9/5/2023

To whom it may concern:

Model Energy, PLLC performed a field inspection on August 29, 2023, to the property located at 101 N. 12th St., Erwin, NC 28339 and has reviewed the installation details of the PV system that was installed by SmartSun. The field inspection was performed by myself, Andrew King (a North Carolina registered design professional), or a person under my direct supervisory control. The review was limited to the structural elements involved in the construction.

The structural installation of the PV system has been designed and inspected, the equipment will not create a negative impact on the building's structural design, including any additional loads imposed (dead, snow, and wind), and is in compliance with the 2018 North Carolina Residential Building Code.

Thank you,

Andrew King, PE

