



111386

111386 6615 Old US Highway 421 FLIC - NASA

Customer Information			
Project ID	111386	Lender	FLIC - NASA
Homeowner Name	111386	Utility Provider	Duke Energy
Street Address	6615 Old US Highway 421	Region	Raleigh
City	Lillington	Processed	No
State	NC	Customer's WiFi Network Name Customer's WiFi Network Password	
Zip Code	27546		
Fleet			
Vehicle Number:	E229	Installer Phone Number:	
Is there anything that needs to be addressed by the fleet team? Please select all that apply.	No	If you have any additional information or if you are selecting 'Other', please provide a brief comment for the Fleet team.	
Safety			
Hazard Identification	None	_	
ESS			
Is this an ESS, Energy Storage System, project?	No	Reason for Incomplete ESS Install	
Was the ESS installed during today's visit?		ESS Manufacturer	

Breakers & Terminations

Type of Interconnection

Breaker

Page 1 of 13 Report Created: 12/05/2023

EMT

Grounding & Bonding				
Is there a natural gas supply? No		Is there PEX pipe on site?	No	
Is a water bond needed?	No			
Exterior of Enclosures				
Were any placards required today?	No			
Additional Equipment				
Was there an existing ATS on site?	No	Was there an EV charger No installed today?		
Was a portable generator plug installed today?	No			
Commissioning				
Is the full solar installation complete?	No	Was the site fully commissioned? If no, provide reasoning.		
Is there a ESS (Energy Storage Solution) on site?	No			
Design				
Was there a call to Hotline made during today's installation? If so, please provide a note regarding the reason for the call.	No	Have there been any design changes made in the field? (Must have Hotline Approval: 512-200-2085)		
Customer Walkthrough				
Is the homeowner or customer representative present, and available for a walkthrough?	Yes	"As we closeout this walkthrough, is there anything you would like our customer experience team to handle that	None	
HO not present, or declined walkthrough.	Call and/or Text the Customer: "We have completed the installation process & are now leaving the residence. Our Customer Care team will be in touch with you shortly to discuss the next steps."	is beyond my expertise?"		
		Homeowner Confirmation:	"We recognize the significance of keeping you well-informed throughout this process. Our dedicated Customer Care team will ensure that you receive	
If declined, request the HO signature.		regular updates concerning the city and utility inspection schedules. These inspections typically require approximately 30-45 days to finalize, as they are coordinated with the utility		
D 0.440			B	

Page 2 of 13 Report Created: 12/05/2023

"Hey there! We're super excited to let you know that your new equipment is fully installed"

"Would you like to accompany me on a walk around your home while I clean up and review the installation? If you notice anything that needs attention, please inform me so I can promptly address it or make a note for further review."

None

provider's availability. Once the utility inspection phase successfully concludes and your utility grants permission to operate, we will proceed with registering your warranty and granting you access to your monitoring services. This represents a significant step forward, providing you with comprehensive visibility and control over your project's advancement. As we approach the final stages, we will conclude the project by inviting you to a virtual launch meeting. During this meeting, we will cover the entire process, including how to energize your system, make effective use of the monitoring services, and supply you with essential tax information. This session is designed to ensure your complete comfort and confidence with every aspect of your new setup. Kindly confirm that all matters have been addressed." Yes

Homeowner Signature

Part Towns

Customer Review:

Link to review: https://www. google.com/search? sca_esv=561932315&q=Freedom

"Before we leave, could you do me a favor and leave a Google Review? Additionally, I wanted to let you know that you'll be receiving a survey within the next few days. This survey will allow you to provide feedback on various topics, including sales, installation, and communication. Your honest feedback would be greatly appreciated!"

Additional Work

Was there any damage incurred during this installation?

No

Is there any other additional work that needs to be addressed?

No

Select all applicable options and provide any relevant notes and photos of the damage(s) identified.

Check all relevant options and provide any necessary notes and photos of the required additional work.

FSP Employee Confirmation

Employee Confirmation

To the best of my knowledge, I confirm that the provided information is accurate and truthful. All requested photos and

Employee Signature

Alls

documentation have been successfully uploaded under the correct Project ID.

Page 4 of 13 Report Created: 12/05/2023

Customer Information / Photo: Street Address



Fleet / Photo of Dashboard/Gauges



Alejandro Rodriguez Loc: **35.4147**, **-78.9293**

Fleet / Parked Truck w/ Safety Cones



Alejandro Rodriguez Loc: **35.4149**, **-78.9292**

Alejandro Rodriguez Loc: **35.4149**, **-78.9293**

Fleet / Inside/Cab of Truck



Alejandro Rodriguez Loc: **35.4149**, **-78.9293**

Page 5 of 13 Report Created: 12/05/2023

Fleet / Back of Truck (Doors Open)



Alejandro Rodriguez Loc: 35.4149, -78.9292

Safety / PPE - Hot Gloves near EQ wall



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Safety / PPE - Face Shield near EQ wall



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Interior of Enclosures / Wide Shot: EQ Wall w/o Deadfronts - Indoor & Outdoor



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**


Page 6 of 13 Report Created: 12/05/2023

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Interior of Enclosures $\slash\hspace{-0.05cm}$ Interior of AC Disconnect (Wiring and fuse sizes visible, if applicable)



Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

Interior of Enclosures / Interior of AC Disconnect (Wiring and fuse sizes visible, if applicable)



Alejandro Rodriguez Loc: **35.4146, -78.9293**

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Page 7 of 13 Report Created: 12/05/2023

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Alejandro Rodriguez Loc: **35.4146, -78.9294**

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Alejandro Rodriguez Loc: **35.4146, -78.9294**

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

Interior of Enclosures / Production CT



Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

Page 8 of 13 Report Created: 12/05/2023

Interior of Enclosures / Consumption CTs



Alejandro Rodriguez Loc: **35.4146, -78.9293**

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Alejandro Rodriguez Loc: 35.4146, -78.9294

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Alejandro Rodriguez Loc: **35.4146, -78.9294**

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

Page 9 of 13 Report Created: 12/05/2023

Breakers & Terminations / Close Up of Breaker



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

 ${\bf EMT\,/\,EMT\,-\,Couplers,\!Connectors,\!Straps,\,Nipples,\!Bend,\,etc.}$




Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

EMT / EMT - Pipedown Location (Roof-to-Wall Transition)



Alejandro Rodriguez Loc: **35.4146**, **-78.9294**

 $\textbf{EMT} \ / \ \textbf{EMT - Couplers,Connectors,Straps, Nipples,Bend, etc.}$



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Page 10 of 13 Report Created: 12/05/2023

 $\operatorname{EMT}/\operatorname{Close}\operatorname{Up}$ of Tightened Couplers, Connectors, & Nipples.



Alejandro Rodriguez Loc: **35.4146, -78.9293**

 $\operatorname{EMT}/\operatorname{Close}$ Up of Tightened Couplers, Connectors, & Nipples.



Alejandro Rodriguez Loc: **35.4146, -78.9293**

EMT / Close Up of Tightened Couplers, Connectors, & Nipples.



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Grounding & Bonding / Ground Rod/GEC



Alejandro Rodriguez Loc: **35.4146, -78.9294**

Page 11 of 13 Report Created: 12/05/2023

Exterior of Enclosures / Main Service Panel w/ Deadfront



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Exterior of Enclosures / Agg Panel w/ Deadfront



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Exterior of Enclosures / Wide Shot of Indoor & Outdoor Electrical Equipment



Exterior of Enclosures / Wide Shot of Indoor & Outdoor Electrical Equipment



Alejandro Rodriguez Loc: **35.4146**, **-78.9294** Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Exterior of Enclosures / Exterior of Main Service Panel (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4146, -78.9293**

Exterior of Enclosures / Exterior of AC Disconnect (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4146, -78.9293**

Exterior of Enclosures / Exterior of Agg Panel (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4146**, **-78.9293**

Exterior of Enclosures / Exterior of Monitoring Equipment




Alejandro Rodriguez Loc: **35.4146, -78.9293**

Page 13 of 13 Report Created: 12/05/2023











6615 Old US Highway 421




Verify your CT installation (2)



LIVE DATA

















Live Data



6615 Old US Highway 421



Power Production


0.00 >

Verify your CT installation (2)

>
















Configure

Live Data



SUCCESS



Commissioning completed successfully at

6615 Old US Highway 421, Lillington, NC

OPEN COMMISSIONING REPORT

CREATE HOMEOWNER ACCOUNT

How was your commissioning experience?




EXIT SITE

LIVE DATA










Configure


Live Data





Discovery Complete

Please make sure to remove any MIs not belonging to the site before continuing.









6615 Old US Highway 421



SYSTEM CONFIGURATION



* Required information for commissioning



The PVS has been successfully commissioned

CONTINUE