

Subject: Photovoltaic Solar Post Construction Structural Inspection

Date: 9/29/23

Project: Batten, James

Address: 95 Old Field Loop, Sanford, NC 27332

To Whom it May Concern,

I, or someone under my responsible charge, have performed a post installation structural inspection of the photovoltaic solar installation at the address listed above. The inspection was limited to the structural elements of the installation only.

This post installation structural inspection verifies:

- 1) The PV equipment's structural installation has been designed and inspected
- 2) The equipment will not create a negative impact on the building's structural design, including any additional loads imposed (dead, snow, wind)
- 3) The installation is in compliance with the North Carolina Residential Code

Andrew King, PE

