



111894

111894 89 Fairfield Lane SunPower

Customer Information			
Project ID	111894	Lender	SunPower
Homeowner Name	111894	Utility Provider	Duke Energy - North Carolina
Street Address	89 Fairfield Lane	Region	Raleigh
City	Lillington	Processed	No
State	NC	Customer's WiFi Network	
Zip Code	27546	Customer's WiFi Network Password	
Fleet			
Vehicle Number:	E180	Installer Phone Number:	3145757300
Is there anything that needs to be addressed by the fleet team?	Yes	If you have any additional information or if you are selecting 'Other', please provide a brief comment for the Fleet team.	Door doesnt close properly. Theres a gap when it closes and it locks but when you drive the sensor reads that the door is still open
Please select all that apply.	Other		
Safety			
Hazard Identification	None		
ESS			
Is this an ESS, Energy Storage System, project?	No	Reason for Incomplete ESS Install	
Was the ESS installed during today's visit?		ESS Manufacturer	

Breakers & Terminations

Type of Interconnection

Breaker

Page 1 of 14 Report Created: 11/10/2023

EMT

Grounding & Bonding			
Is there a natural gas supply?	No	Is there PEX pipe on site?	No
Is a water bond needed?	No		
Exterior of Enclosures			
Were any placards required today?	No		
Additional Equipment			
Was there an existing ATS on site?	No	Was there an EV charger No installed today?	No
Was a portable generator plug installed today?	No		
Commissioning			
Is the full solar installation complete?	No	Was the site fully commissioned? If no, provide	
Is there a ESS (Energy Storage Solution) on site?	No	reasoning.	
Design			_
Was there a call to Hotline made during today's installation? If so, please provide a note regarding the reason for the call.	No	Have there been any design changes made in the field? (Must have Hotline Approval: 512-200-2085)	No - Built as Designed
Customer Walkthrough			
Is the homeowner or customer representative present, and available for a walkthrough?	Yes	"As we closeout this walkthrough, is there anything you would like our customer experience team to handle that	None
HO not present, or declined walkthrough.	Call and/or Text the Customer: "We have completed the installation process & are now leaving the residence. Our Customer Care team will be in touch with you shortly to discuss the next steps."	is beyond my expertise?"	
		Homeowner Confirmation:	"We recognize the significance of keeping you well-informed throughout this process. Our dedicated Customer Care team will ensure that you receive regular updates concerning the city and utility inspection schedules. These inspections typically require approximately 30-45 days to finalize, as they are coordinated with the utility
If declined, request the HO signature.			
D 0.444			D O

Page 2 of 14 Report Created: 11/10/2023

"Hey there! We're super excited to let you know that your new equipment is fully installed"

"Would you like to accompany me on a walk around your home while I clean up and review the installation? If you notice anything that needs attention, please inform me so I can promptly address it or make a note for further review."

None

provider's availability. Once the utility inspection phase successfully concludes and your utility grants permission to operate, we will proceed with registering your warranty and granting you access to your monitoring services. This represents a significant step forward, providing you with comprehensive visibility and control over your project's advancement. As we approach the final stages, we will conclude the project by inviting you to a virtual launch meeting. During this meeting, we will cover the entire process, including how to energize your system, make effective use of the monitoring services, and supply you with essential tax information. This session is designed to ensure your complete comfort and confidence with every aspect of your new setup. Kindly confirm that all matters have been addressed." Yes

Homeowner Signature

MS/carins

Customer Review:

Link to review: https://www. google.com/search? sca_esv=561932315&q=Freedom

"Before we leave, could you do me a favor and leave a Google Review? Additionally, I wanted to let you know that you'll be receiving a survey within the next few days. This survey will allow you to provide feedback on various topics, including sales, installation, and communication. Your honest feedback would be greatly appreciated!"

Additional Work

Was there any damage incurred during this installation?

No

Is there any other additional work that needs to be addressed?

No

Select all applicable options and provide any relevant notes and photos of the damage(s) identified.

Check all relevant options and provide any necessary notes and photos of the required additional work.

FSP Employee Confirmation

Employee Confirmation

To the best of my knowledge, I confirm that the provided information is accurate and truthful. All requested photos and

Employee Signature

AM

documentation have been successfully uploaded under the correct Project ID.

Page 4 of 14 Report Created: 11/10/2023

Customer Information / Photo: Street Address



Fleet / Photo of Dashboard/Gauges



Alejandro Rodriguez Loc: 35.4557, -78.7809

Alejandro Rodriguez Loc: **35.4556**, **-78.781**

Fleet / Photo of Fleet Issue(s)



Alejandro Rodriguez Loc: 35.4557, -78.781

Fleet / Photo of Fleet Issue(s)



Alejandro Rodriguez Loc: **35.4557**, **-78.781**


Page 5 of 14 Report Created: 11/10/2023

Fleet / Photo of Fleet Issue(s)



Alejandro Rodriguez Loc: **35.4558, -78.7809**

Fleet / Inside/Cab of Truck



Alejandro Rodriguez Loc: **35.4558**, **-78.7809**

Fleet / Parked Truck w/ Safety Cones



Alejandro Rodriguez Loc: **35.4558**, **-78.781**

Fleet / Back of Truck (Doors Open)



Alejandro Rodriguez Loc: **35.4557**, **-78.781**

Page 6 of 14 Report Created: 11/10/2023

Safety / PPE - Face Shield near EQ wall



Safety / PPE - Hot Gloves near EQ wall



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Interior of Enclosures / Wide Shot: EQ Wall w/o Deadfronts - Indoor & Outdoor



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Page 7 of 14 Report Created: 11/10/2023

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Alejandro Rodriguez Loc: **35.4555, -78.7811**

Interior of Enclosures $\slash\hspace{-0.6em}$ Interior of AC Disconnect (Wiring and fuse sizes visible, if applicable)



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Interior of Enclosures / Production CT



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Page 8 of 14 Report Created: 11/10/2023

Interior of Enclosures / Consumption CTs



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Interior of Enclosures $\slash\hspace{-0.05cm}$ Close Up of Monitoring Equipment (Wiring & serial number)



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Breakers & Terminations / Close Up of Breaker



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Page 9 of 14 Report Created: 11/10/2023

EMT / EMT - Pipedown Location (Roof-to-Wall Transition)



 ${\bf EMT\,/\,EMT\,-\,Couplers,\!Connectors,\!Straps,\,Nipples,\!Bend,\,etc.}$



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

EMT / EMT - Couplers, Connectors, Straps, Nipples, Bend, etc.



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**


 ${\bf EMT\ /\ EMT\ -\ Couplers, Connectors, Straps,\ Nipples, Bend,\ etc.}$



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Page 10 of 14 Report Created: 11/10/2023

 ${\bf EMT\ /\ EMT\ -\ Couplers, Connectors, Straps,\ Nipples, Bend,\ etc.}$



 $\operatorname{EMT}/\operatorname{Close}$ Up of Tightened Couplers, Connectors, & Nipples.



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

EMT / EMT - Couplers, Connectors, Straps, Nipples, Bend, etc.



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

 $\operatorname{EMT}/\operatorname{Close}$ Up of Tightened Couplers, Connectors, & Nipples.



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Page 11 of 14 Report Created: 11/10/2023

EMT / Close Up of Tightened Couplers, Connectors, & Nipples.



Exterior of Enclosures / Main Service Panel w/ Deadfront



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Grounding & Bonding / Ground Rod/GEC



Alejandro Rodriguez Loc: 35.4555, -78.7808

Exterior of Enclosures / Agg Panel w/ Deadfront



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Page 12 of 14 Report Created: 11/10/2023

Exterior of Enclosures / Wide Shot of Indoor & Outdoor Electrical Equipment



Exterior of Enclosures / Exterior of Main Service Panel (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Alejandro Rodriguez Loc: **35.4555, -78.7809**

Exterior of Enclosures / Exterior of AC Disconnect (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4555, -78.7809**

Exterior of Enclosures / Exterior of AC Disconnect (Labeled w/ Stickers)



Alejandro Rodriguez Loc: **35.4555**, **-78.7809**

Page 13 of 14 Report Created: 11/10/2023

Exterior of Enclosures / Exterior of Agg Panel (Labeled w/ Stickers)



Alejandro Rodriguez Loc: 35.4555, -78.7809

Exterior of Enclosures / Exterior of Monitoring Equipment



Alejandro Rodriguez Loc: 35.4555, -78.7809

Page 14 of 14 Report Created: 11/10/2023

