

Hazard Identification

None

113690113690

113690 416 Wire Road GreenSky

Customer Information			
Project ID	113690	Lender	GreenSky
	Automated Populated Value		Automated Populated Value
Homeowner Name	113690	Utility Provider	Duke Energy - North Carolina
	Automated Populated Value		Automated Populated Value
Street Address	416 Wire Road	Region	Raleigh
	Automated Populated Value		Automated Populated Value
City	Bunnlevel, NC	Processed	No
	Automated Populated Value	Customer's WiFi Network	
State	NC	Name	
	Automated Populated Value	Customer's WiFi Network Password	
Zip Code	283823	=	
	Automated Populated Value		
Fleet			
Vehicle Number:	253	Please select all that apply.	
Vehicle Type:	Cargo Van	Installer Phone Number:	
Is there anything that needs to be addressed by the fleet team?	No	Provide a concise description of the problems to assist the Fleet department in swiftly addressing the issue(s).	

Page 1 of 15 Report Created: 05/22/2024

Tesla Storage			
Is there a Tesla Gateway or Backup Switch being installed today?	Yes	Tesla Powerwall Type:	Powerwall 2
nterior of Enclosures			
Breakers & Terminations			
Type of Interconnection	Mech Lug		
ЕМТ			
Grounding & Bonding			
Is there a natural gas supply?	No	Is there PEX pipe on site?	
Is there metal plumbing?	No		
Exterior of Enclosures			
Were any placards required today?	No		
Additional Equipment			
Was there an existing ATS on site?	No	Was there an EV charger installed today?	No
Was a portable generator plug installed today?	No		
Commissioning			
What type of solar system is installed?	AC	Has the Tesla equipment been commissioned?	Yes
Is the AC solar install complete?	No	Provide brief reasoning for the site not being commissioned.	
Design			
Was there a call to Hotline made during today's installation? If so, please provide a note regarding the reason for the call.	Yes	Have there been any design changes made in the field? (Must have Hotline Approval: 512-200-2085)	No - Built as Designed

Page 2 of 15 Report Created: 05/22/2024

Is the homeowner or customer representative present, and available for a walkthrough?

No

HO not present, or declined walkthrough.

Call and/or Text the Customer:
"We have completed the
installation process & are now
leaving the residence. Our
Customer Care team will be in
touch with you shortly to discuss
the next steps."

If declined, request the HO signature.

"Hey there! We're super excited to let you know that your new equipment is fully installed"

"Would you like to accompany me on a walk around your home while I clean up and review the installation? If you notice anything that needs attention, please inform me so I can promptly address it or make a note for further review." "As we closeout this walkthrough, is there anything you would like our customer experience team to handle that is beyond my expertise?"

Homeowner Confirmation:

"We recognize the significance of keeping you well-informed throughout this process. Our dedicated Customer Care team will ensure that you receive regular updates concerning the city and utility inspection schedules. These inspections typically require approximately 30-45 days to finalize, as they are coordinated with the utility provider's availability. Once the utility inspection phase successfully concludes and your utility grants permission to operate, we will proceed with registering your warranty and granting you access to your monitoring services. This represents a significant step forward, providing you with comprehensive visibility and control over your project's advancement. As we approach the final stages, we will conclude the project by inviting you to a virtual launch meeting. During this meeting, we will cover the entire process, including how to energize your system, make effective use of the monitoring services, and supply you with essential tax information. This session is designed to ensure your complete comfort and confidence with every aspect of your new setup. Kindly confirm that all matters have been addressed."

Homeowner Signature

Customer Review:

Link to review: https://www. google.com/search? sca_esv=561932315&q=Freedom

"Before we leave, could you do me a favor and leave a Google Review? Additionally, I wanted to let you know that you'll be receiving a survey within the next few days. This survey will allow you to provide feedback on various topics, including sales, installation, and communication. Your honest feedback would be greatly appreciated!"

Additional Work

Page 3 of 15 Report Created: 05/22/2024

Was there any damage incurred during this installation?

No

Is there any other additional work that needs to be addressed?

No

Select all applicable options and provide any relevant notes and photos of the damage(s) identified. Check all relevant options and provide any necessary notes and photos of the required additional work.

FSP Employee Confirmation

Employee Confirmation


To the best of my knowledge, I confirm that the provided information is accurate and truthful. All requested photos and documentation have been successfully uploaded under the correct Project ID.

Employee Signature



Page 4 of 15 Report Created: 05/22/2024

Customer Information / Photo: Street Address




Benjamin Davis Loc: **36.0082**, **-78.9373**

Fleet / Parked Truck w/ Safety Cones



Benjamin Davis

Fleet / Photo of Dashboard/Gauges



Benjamin Davis Loc: **36.0082**, **-78.9373**

Fleet / Inside/Cab of Truck



Benjamin Davis

Page 5 of 15 Report Created: 05/22/2024

Fleet / Back of Truck (Doors Open)



Benjamin Davis

Safety / PPE - Hot Gloves near EQ wall




Benjamin Davis

Safety / PPE - Face Shield near EQ wall



Benjamin Davis

Tesla Storage / Tesla Gateway, or Switch, Interior



Benjamin Davis


Page 6 of 15 Report Created: 05/22/2024

Tesla Storage / Backup Gateway, or Switch, Serial Number



Benjamin Davis

Tesla Storage / Powerwall Location




Benjamin Davis

Tesla Storage / Tesla Gateway Deadfront (Labeled w/ Stickers)



Benjamin Davis

Tesla Storage / Powerwall Mounting Bracket Installed



Benjamin Davis

Page 7 of 15 Report Created: 05/22/2024

Tesla Storage / Tesla P/W Wiring Compartment



Benjamin Davis

Tesla Storage / Tesla P/W Wiring Compartment



Benjamin Davis

Tesla Storage / Tesla P/W Serial Number(s)



Benjamin Davis

Tesla Storage / Tesla P/W Serial Number(s)



Benjamin Davis

Page 8 of 15 Report Created: 05/22/2024

Tesla Storage / Powerwall 2 - Tesla Production CT



Benjamin Davis

Tesla Storage / Powerwall 2 - Tesla Consumption CT (Factory & Field Installed)



Benjamin Davis

Interior of Enclosures / Wide Shot: EQ Wall w/o Deadfronts - Indoor & Outdoor



Benjamin Davis

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Benjamin Davis Loc: **35.3133, -78.7962**


Page 9 of 15 Report Created: 05/22/2024

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Benjamin Davis Loc: **35.3133, -78.7962**

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Benjamin Davis Loc: **35.3133**, **-78.7962**

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Benjamin Davis Loc: **35.3133**, **-78.7962**

Interior of Enclosures / Interior of AC Disconnect (Wiring and fuse sizes visible, if applicable)



Benjamin Davis


Page 10 of 15 Report Created: 05/22/2024

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Benjamin Davis

Breakers & Terminations $\slash\hspace{-0.6em}$ Close Up of Mech. Lugs Fully Torqued w/ marks visible




Benjamin Davis

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Benjamin Davis


EMT / EMT - Pipedown Location (Roof-to-Wall Transition)



Benjamin Davis Loc: **36.0082**, **-78.9373**

Page 11 of 15 Report Created: 05/22/2024

 ${\bf EMT\,/\,EMT\,-\,Couplers,\!Connectors,\!Straps,\,Nipples,\!Bend,\,etc.}$




Benjamin Davis Loc: **36.0082**, **-78.9373**

Exterior of Enclosures / Main Service Panel w/ Deadfront



Benjamin Davis

Grounding & Bonding / Ground Rod/GEC



Benjamin Davis Loc: **36.0082**, **-78.9373**

Exterior of Enclosures / Agg Panel w/ Deadfront



Benjamin Davis

Page 12 of 15 Report Created: 05/22/2024

Exterior of Enclosures / Wide Shot of Indoor & Outdoor Electrical Equipment



Exterior of Enclosures / Exterior of Main Service Panel (Labeled w/ Stickers)



Benjamin Davis Loc: **35.3133**, **-78.7962**

Benjamin Davis

Exterior of Enclosures / Exterior of Main Service Panel (Labeled w/ Stickers)



Benjamin Davis Loc: **35.3133, -78.7962**

Exterior of Enclosures / Exterior of AC Disconnect (Labeled w/ Stickers)



Benjamin Davis

Page 13 of 15 Report Created: 05/22/2024

Exterior of Enclosures / Exterior of Monitoring Equipment




Benjamin Davis

Commissioning / Tesla Meter Configurations (Screenshot)




Benjamin Davis

Commissioning / Tesla Registration (Screenshot) - 'Freedom Solar LLC.'



Benjamin Davis


Commissioning / Tesla Meter Configurations (Screenshot)



Benjamin Davis

Page 14 of 15 Report Created: 05/22/2024

Commissioning / Tesla Meter Configurations (Screenshot)



Benjamin Davis

Page 15 of 15 Report Created: 05/22/2024