



Princeton Engineering P. C.
Solar, Structural, Electrical and Site Engineering

Date: 06/26/2024

AHJ: Harnett County

Re: PV Solar Post Installation Structural Certification
Solar Installer: Freedom Solar, LLC, 4801 Freidrich Ln, Austin, TX 78744
Customer Name: CURTIS COLLINS
Customer Address: 728 COLLINS ROAD, LILLINGTON, NC, 27546
Permit Number: ERES2404-0006
PE Project Number: 36.114123
PE Structural Report Date: 6/26/2024

To Code Enforcement Officials:


We prepared a structural assessment of the roof framing for the referenced PV solar panel installation, to determine the adequacy of the roof to support this system. The analysis used the maximum spacing of the PV support points and was based upon the wind and snow loadings indicated by the ASCE. The framing size and spacing was verified to match the size and spacing used in our analysis.

In summary, we analyzed the roof structure by combining the existing dead and live loads, along with the new PV solar panels and found the roof to be adequate to support this new PV solar system as indicated in our structural assessment report. On site personnel inspected the installation and found that the panel support locations and spacing generally conform to that used in preparation of the structural assessment report. No existing or new damage to any structural element was observed.

The PV equipment's structural installation has been inspected and will not create a negative impact on the building's structural design, and the installation is in compliance with the North Carolina Residential Code.

Regards,

Richard J. Pantel, P.E.
NC License No. 043326



06/27/2024

Pantel NC Affidavit Structural 20230808.docx