

# RIGHT ANGLE *ENGINEERING*

## Structural Installation Inspection

5 June 2024

### Poly Energy

174 Corley Mill Rd  
Lexington, SC 29072

RE: Structural Solar Installation Inspection for the *Whitaker Residence: 105 Wrench St Erwin, NC 28339*

An inspection of the structural components of the installed solar system was performed by Right Angle Engineering. It is our opinion that the installation was performed in accordance with the approved building plans dated 4/16/24. The structural components appear to be in compliance with the adopted building codes.

Please feel free to contact me for clarification or additional information.

Sincerely,

Robert Smythe, PE

