



115404

115404 105 Micahs Way North Sunlight

| Customer Information | | | |
|--|----------------------|--|-----------------|
| Project ID | 115404 | Lender | Sunlight |
| Homeowner Name | 115404 | Utility Provider | South River EMO |
| Street Address | 105 Micahs Way North | Region | Raleigh |
| City | Spring Lake | Processed | No |
| State | NC | Customer's WiFi Network | |
| Zip Code | 28390 | Customer's WiFi Network Password | |
| Fleet | | | |
| Vehicle Number: | E292 | Please select all that apply. | |
| Vehicle Type: | Cargo Van | Installer Phone Number: | |
| Is there anything that needs to be addressed by the fleet team? | No | Provide a concise description of the problems to assist the Fleet department in swiftly addressing the issue(s). | |
| Safety | | | |
| Hazard Identification | None | | |
| Tesla Storage | | | |
| Is there a Tesla Gateway or Backup Switch being installed today? | No | Tesla Powerwall Type: | |

Interior of Enclosures

Page 1 of 14 Report Created: 09/24/2024

| Breakers & Terminations | | | |
|---|--|--|--|
| Type of Interconnection | IPCs | | |
| EMT | | | |
| Grounding & Bonding | | | |
| Is there a natural gas supply? | No | Is there PEX pipe on site? | |
| Is there metal plumbing? | No | | |
| Exterior of Enclosures | | | |
| Were any placards required today? | No | | |
| Additional Equipment | | | |
| Was there an existing ATS on site? | No | Was there an EV charger installed today? | No |
| Was a portable generator plug installed today? | No | | |
| Commissioning | | | |
| What type of solar system is installed? | AC | Has the Tesla equipment been commissioned? | |
| Is the AC solar install complete? | Yes | Provide brief reasoning for the site not being commissioned. | |
| Design | | | |
| Was there a call to Hotline made during today's installation? If so, please provide a note regarding the reason for the call. | No | Have there been any design changes made in the field? (Must have Hotline Approval: 512-200-2085) | No - Built as Designed |
| Customer Walkthrough | | | |
| Is the homeowner or customer representative present, and available for a walkthrough? | Yes | "As we closeout this walkthrough, is there anything you would like our customer experience team to handle that | None |
| HO not present, or declined walkthrough. | Call and/or Text the Customer: "We have completed the installation process & are now leaving the residence. Our Customer Care team will be in touch with you shortly to discuss the next steps." | is beyond my expertise?" Homeowner Confirmation: | "We recognize the significance of keeping you well-informed throughout this process. Our dedicated Customer Care team will ensure that you receive |
| Page 2 of 14 | • | | Report Created: 09/24/2024 |

Page 2 of 14 Report Created: 09/24/2024

If declined, request the HO signature.

"Hey there! We're super excited to let you know that your new equipment is fully installed"

"Would you like to accompany me on a walk around your home while I clean up and review the installation? If you notice anything that needs attention, please inform me so I can promptly address it or make a note for further review."

None

regular updates concerning the city and utility inspection schedules. These inspections typically require approximately 30-45 days to finalize, as they are coordinated with the utility provider's availability. Once the utility inspection phase successfully concludes and your utility grants permission to operate, we will proceed with registering your warranty and granting you access to your monitoring services. This represents a significant step forward, providing you with comprehensive visibility and control over your project's advancement. As we approach the final stages, we will conclude the project by inviting you to a virtual launch meeting. During this meeting, we will cover the entire process, including how to energize vour system, make effective use of the monitoring services, and supply you with essential tax information. This session is designed to ensure your complete comfort and confidence with every aspect of your new setup. Kindly confirm that all matters have been addressed." Yes

Homeowner Signature

BT

Customer Review:

Link to review: https://www. google.com/search? sca_esv=561932315&q=Freedom

"Before we leave, could you do me a favor and leave a Google Review? Additionally, I wanted to let you know that you'll be receiving a survey within the next few days. This survey will allow you to provide feedback on various topics, including sales, installation, and communication. Your honest feedback would be greatly appreciated!"

Additional Work

Was there any damage incurred during this installation?

No

Is there any other additional work that needs to be addressed?

No

Select all applicable options and provide any relevant notes and photos of the damage(s) identified.

Check all relevant options and provide any necessary notes and photos of the required additional work.

Page 3 of 14 Report Created: 09/24/2024

FSP Employee Confirmation

Employee Confirmation

To the best of my knowledge, I confirm that the provided information is accurate and truthful. All requested photos and documentation have been successfully uploaded under the correct Project ID. Yes

Employee Signature

X


Page 4 of 14 Report Created: 09/24/2024

Customer Information / Photo: Street Address



Anthony Medina Loc: **35.2921, -78.974**

Fleet / Parked Truck w/ Safety Cones




Anthony Medina Loc: **35.2921, -78.9742**

Fleet / Photo of Dashboard/Gauges



Anthony Medina Loc: **35.2922, -78.9742**

Fleet / Inside/Cab of Truck



Anthony Medina Loc: **35.2921, -78.9742**

Page 5 of 14 Report Created: 09/24/2024

Fleet / Back of Truck (Doors Open)



Anthony Medina Loc: **35.2921, -78.9742**

Safety / PPE - Hot Gloves near EQ wall



Anthony Medina Loc: **35.2921, -78.9742**

Safety / PPE - Face Shield near EQ wall



Anthony Medina Loc: **35.2921, -78.9742**

Interior of Enclosures / Wide Shot: EQ Wall w/o Deadfronts - Indoor & Outdoor



Anthony Medina Loc: **35.2922, -78.9742**

Page 6 of 14 Report Created: 09/24/2024

Interior of Enclosures / Interior of Main Service Panel w/o Deadfront



Anthony Medina Loc: **35.2922, -78.9742**

Interior of Enclosures / Interior of AC Disconnect (Wiring and fuse sizes visible, if applicable)



Anthony Medina Loc: **35.2922, -78.9742**

Interior of Enclosures / Interior of Agg Panel w/o Deadfront (Wiring & breaker sizes, if applicable)



Anthony Medina Loc: **35.2922**, **-78.9742**


Interior of Enclosures / Production CT, if applicable.



Anthony Medina Loc: **35.2922**, **-78.9742**

Page 7 of 14 Report Created: 09/24/2024

Interior of Enclosures / Consumption CTs, if applicable.



Anthony Medina Loc: **35.2922**, **-78.9742**

Breakers & Terminations / Close Up of IPCs Fully Torqued w/ marks visible (Taps in Main Panel & Fuses in Disconnect)



Anthony Medina Loc: **35.2922**, **-78.9742**

Interior of Enclosures / Close Up of Monitoring Equipment (Wiring & serial number)



Anthony Medina Loc: **35.2922, -78.9743**

EMT / EMT - Pipedown Location (Roof-to-Wall Transition)



Anthony Medina Loc: **35.2922, -78.9742**

Page 8 of 14 Report Created: 09/24/2024

 ${\bf EMT\ /\ EMT\ -\ Couplers, Connectors, Straps,\ Nipples, Bend,\ etc.}$



Anthony Medina Loc: **35.2922, -78.9742**

 ${\bf EMT\,/\,EMT\,-\,Couplers,\!Connectors,\!Straps,\,Nipples,\!Bend,\,etc.}$



Anthony Medina Loc: **35.2922, -78.9742**

EMT / EMT - Couplers, Connectors, Straps, Nipples, Bend, etc.



Anthony Medina Loc: **35.2922, -78.9742**

 ${\bf EMT\ /\ EMT\ -\ Couplers, Connectors, Straps,\ Nipples, Bend,\ etc.}$



Anthony Medina Loc: **35.2922, -78.9742**

Page 9 of 14 Report Created: 09/24/2024

Grounding & Bonding / Ground Rod/GEC



Anthony Medina Loc: **35.2922**, **-78.9742**

Exterior of Enclosures / Agg Panel w/ Deadfront



Anthony Medina Loc: **35.2922, -78.9742**

Exterior of Enclosures / Main Service Panel w/ Deadfront



Anthony Medina Loc: **35.2922**, **-78.9742**

Exterior of Enclosures / Wide Shot of Indoor & Outdoor Electrical Equipment



Anthony Medina Loc: **35.2922, -78.9742**

Page 10 of 14 Report Created: 09/24/2024

Exterior of Enclosures / Exterior of Main Service Panel (Labeled w/ Stickers)



Anthony Medina Loc: **35.2922**, **-78.9742**

Exterior of Enclosures / Exterior of AC Disconnect (Labeled w/ Stickers)




Anthony Medina Loc: **35.2922, -78.9742**

Exterior of Enclosures / Exterior of Monitoring Equipment



Anthony Medina Loc: **35.2922**, **-78.9742**

Commissioning / All MIs Discovered (Screenshot)



Anthony Medina


Page 11 of 14 Report Created: 09/24/2024

Commissioning / All MIs Discovered (Screenshot)



Anthony Medina

Commissioning / All MIs Discovered (Screenshot)



Anthony Medina

Commissioning / All MIs Discovered (Screenshot)



Anthony Medina


Commissioning / All MIs Discovered (Screenshot)



Anthony Medina

Page 12 of 14 Report Created: 09/24/2024

Commissioning / All MIs Discovered (Screenshot)



Anthony Medina

Commissioning / PV ON - Live Data (Solar, Consumption, & Grid in the commissioning app with the solar ON)



Anthony Medina

Commissioning / PV ON - Live Data (Solar, Consumption, & Grid in the commissioning app with the solar ON)



Anthony Medina

Commissioning / PV OFF - Live Data (Solar, Consumption, & Grid in the commissioning app with the solar OFF)



Anthony Medina

Page 13 of 14 Report Created: 09/24/2024

Commissioning / PV OFF - Live Data (Solar, Consumption, & Grid in the commissioning app with the solar OFF)



Anthony Medina

Page 14 of 14 Report Created: 09/24/2024