



**Gregory Jensen** 197 Cooper Creek Ave. Spring Lake, NC 28390

Homeowner information				
Homeowner Name	Gregory Jensen	Date of Installation	03/25/2025	
Address	197 Cooper Creek Ave. Spring Lake, NC 28390			
Glass Pictures/Panel In	fo			
Attic				
Electrical Equipment				
Fuse Rating	40	MEP: Nameplate with busk rating	oar	
Roof				
Final Signoff				
Customer Completion Signature		Change Order		
Crew lead on site		Installers On Site		
Optional Installer Notes				

Page 1 of 217 Report Created: 03/27/2025



Loc: **35.9948**, **-79.7473** 

Page 2 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass pic: Full array



Loc: **35.3222, -79.0918** 

Page 3 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass pic: Full array



Loc: **35.3222, -79.0918** 

Page 4 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass pic: Full array




Loc: **35.3222, -79.0918** 

Page 5 of 217 Report Created: 03/27/2025



Page 6 of 217 Report Created: 03/27/2025




Page 7 of 217 Report Created: 03/27/2025



Page 8 of 217 Report Created: 03/27/2025



Page 9 of 217 Report Created: 03/27/2025




Page 10 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass Pic: From rooftop showing arrays




Page 11 of 217 Report Created: 03/27/2025




Page 12 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass Pic: From rooftop showing arrays



Page 13 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass Pic: From rooftop showing arrays



Page 14 of 217 Report Created: 03/27/2025



Page 15 of 217 Report Created: 03/27/2025




Page 16 of 217 Report Created: 03/27/2025




Page 17 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass Pic: From rooftop showing arrays




Page 18 of 217 Report Created: 03/27/2025




Page 19 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Glass Pic: From rooftop showing arrays



Page 20 of 217 Report Created: 03/27/2025



Page 21 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Back of panel: W/ customer name and panel label up close.



Loc: **35.9978, -79.7575** 

Page 22 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Back of panel: W/ customer name and panel label up close.



Loc: **35.9978, -79.7575** 

Page 23 of 217 Report Created: 03/27/2025

Glass Pictures/Panel Info / Back of panel: W/ customer name and panel label up close.



Loc: 35.9978, -79.7575

Glass Pictures/Panel Info / Back of panel with name and label next to front door or landmark



Loc: **35.9976, -79.7696** 

Page 25 of 217 Report Created: 03/27/2025

## Glass Pictures/Panel Info / Back of Panel (Module Label)



Loc: 35.9988, -79.7748

Glass Pictures/Panel Info / Back of Panel (Module Label)



Loc: 35.9988, -79.7748

Glass Pictures/Panel Info / Back of Panel (Module Label)



Loc: 35.9988, -79.7748

Glass Pictures/Panel Info / Back of Panel (Output Info)



Loc: 36.0005, -79.782

Page 26 of 217 Report Created: 03/27/2025

## Glass Pictures/Panel Info / Back of Panel (Output Info)



Loc: **36.0005**, **-79.782** 

Glass Pictures/Panel Info / Back of Panel (Output Info)




Loc: 36.0005, -79.782

Glass Pictures/Panel Info / Back of Panel (Output Info)



Loc: 36.0005, -79.782

Attic / Entry point of conduit



Loc: 36.0005, -79.7998

Page 27 of 217 Report Created: 03/27/2025

Attic / Entry point of conduit



Loc: **36.0005, -79.7998** 



Attic / Entry point of conduit



Loc: **36.0005**, **-79.7998** 

Attic / Sealed entry point



Page 28 of 217 Report Created: 03/27/2025

Attic / Sealed entry point



Attic / Sealed entry point




Attic / Attic conduit runs (3-4 images)



Loc: 36.0009, -79.8088

Attic / Attic conduit runs (3-4 images)



Loc: 36.0009, -79.8088

Page 29 of 217 Report Created: 03/27/2025

Attic / Attic conduit runs (3-4 images)



Loc: **36.0009, -79.8088** 

Page 30 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 31 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 32 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 33 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 34 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)




Page 35 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 36 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 37 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 38 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 39 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 40 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 41 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 42 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 43 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 44 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)




Page 45 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)




Page 46 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 47 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 48 of 217 Report Created: 03/27/2025

Attic / PV Label/Stickers on Conduit in attic (PV5-label 1)



Page 49 of 217 Report Created: 03/27/2025

Electrical Equipment / Mounted Electrical Equipment on house/ Installation Layout (8ft back with address card)



Loc: **35.9501, -80.5428** 

Page 50 of 217 Report Created: 03/27/2025

Electrical Equipment / Mounted Electrical Equipment on house/ Installation Layout (8ft back with address card)



Loc: **35.9501, -80.5428** 

Page 51 of 217 Report Created: 03/27/2025

Electrical Equipment / Mounted Electrical Equipment on house/ Installation Layout (8ft back with address card)



Loc: **35.9501, -80.5428** 

Page 52 of 217 Report Created: 03/27/2025

Electrical Equipment / Mounting bracket



Loc: **35.9435**, **-80.5565** 


Page 53 of 217 Report Created: 03/27/2025

Electrical Equipment / Inverter nameplate with address card



Loc: **35.9397, -80.5639** 

Page 54 of 217 Report Created: 03/27/2025



Loc: **35.9397**, **-80.5639** 

## Electrical Equipment / Inverter-inside wiring



Loc: 35.9344, -80.5721

Electrical Equipment / Inverter-inside wiring



Loc: 35.9344, -80.5721

Electrical Equipment / Inverter-inside wiring



Loc: 35.9344, -80.5721


Electrical Equipment / Inverter-inside wiring



Loc: 35.9344, -80.5721

Page 56 of 217 Report Created: 03/27/2025

# Electrical Equipment / Inverter-inside wiring




Loc: 35.9344, -80.5721

# Electrical Equipment / Inverter-inside wiring



Loc: **35.9344, -80.5721** 

Electrical Equipment / Inverter-inside wiring



Loc: **35.9344**, **-80.5721** 

**Electrical Equipment / Wiring Terminations** 



Loc: 35.9279, -80.5824

Page 57 of 217 Report Created: 03/27/2025

# **Electrical Equipment / Wiring Terminations**




Loc: 35.9279, -80.5824



Loc: 35.9279, -80.5824

**Electrical Equipment / Wiring Terminations** 



Loc: **35.9279**, **-80.5824** 

**Electrical Equipment / Wiring Terminations** 



Loc: **35.9279**, **-80.5824** 

Page 58 of 217 Report Created: 03/27/2025

# **Electrical Equipment / Wiring Terminations**



Loc: 35.9279, -80.5824

Electrical Equipment / Bonding Bushing inside inverter




Loc: 35.9238, -80.589

Electrical Equipment / Bonding Bushing inside inverter



Loc: **35.9238, -80.589** 

Electrical Equipment / Bonding Bushing inside inverter



Loc: 35.9238, -80.589

Page 59 of 217 Report Created: 03/27/2025

# Electrical Equipment / Ground Lug inside inverter



Loc: **35.9209**, **-80.5943** 

Electrical Equipment / Ground Lug inside inverter



Loc: **35.9209, -80.5943** 

Electrical Equipment / Ground Lug inside inverter



Loc: **35.9209**, **-80.5943** 

Page 60 of 217 Report Created: 03/27/2025

Electrical Equipment / PV Label/Sticker on Inverter (PV5-Label 3)



Loc: **35.9176, -80.6014** 

Page 61 of 217 Report Created: 03/27/2025

Electrical Equipment / Disconnect - With cover open



Loc: 35.9116, -80.6139

Electrical Equipment / Disconnect - With cover open



Loc: **35.9116**, **-80.6139** 

Electrical Equipment / Disconnect - With cover open



Loc: **35.9116**, **-80.6139** 

Electrical Equipment / Disconnect - With cover open



Loc: 35.9116, -80.6139

Page 62 of 217 Report Created: 03/27/2025

Electrical Equipment / Disconnect - With cover open



Loc: 35.9116, -80.6139

Electrical Equipment / Disconnect - With cover open



Loc: **35.9116**, **-80.6139** 

Electrical Equipment / Disconnect - With cover open



Loc: **35.9116**, **-80.6139** 


Electrical Equipment / Bonding Bushing in AC disconnect (2)



Loc: 35.906, -80.6255

Page 63 of 217 Report Created: 03/27/2025

**Electrical Equipment / Bonding Bushing in AC disconnect (2)** 



Loc: **35.906, -80.6255** 

Electrical Equipment / Ground lug inside Disconnect



Loc: 35.9036, -80.6307

Electrical Equipment / Ground lug inside Disconnect



Loc: 35.9036, -80.6307

Electrical Equipment / Seal around exterior of conduit on DISCO



Loc: 35.9008, -80.6391

Page 64 of 217 Report Created: 03/27/2025

Electrical Equipment / Seal around exterior of conduit on DISCO



Loc: 35.9008, -80.6391


Page 65 of 217 Report Created: 03/27/2025



Loc: **35.8968**, **-80.6493** 

Page 66 of 217 Report Created: 03/27/2025

Electrical Equipment / Main Electrical Panel (MEP) with address card (One per applicable panel)



Page 67 of 217 Report Created: 03/27/2025

Electrical Equipment / Main Electrical Panel (MEP) with address card (One per applicable panel)




Page 68 of 217 Report Created: 03/27/2025

Electrical Equipment / Main Electrical Panel (MEP) with address card (One per applicable panel)




Page 69 of 217 Report Created: 03/27/2025

Electrical Equipment / Main Electrical Panel (MEP) with address card (One per applicable panel)




Page 70 of 217 Report Created: 03/27/2025



Page 71 of 217 Report Created: 03/27/2025


	N1101.9 or	EFFICIENCY CERTIFICATE NCECC 401.3 Endently verified to meet the D12 NC ENERGY CONSERVATION CODE
-	PROPERTY ADDRESS 197 Co	OPER CREAK AVE.
	BUILDER SIGNATURE	BUILDING AIR LEAKAGE
	CEILING/ROOF R-VALUE*	Visually inspected according to §N1102.4.2.1 or §NCECC 402.4.2.1
	WALL 19	AND / OR Building Air Leakage Test
	FLOOR CLOSED CRAWL WALL	Results (§N1102.4.2.2) (TARGET: $\leq$ 5 ACH50)  ACH5
	CLOSED CRAWL FLOOR	HVAC DUCTS R-VALUE*
	(IF APPLICABLE)  SLAB	INSULATION (Cond.)
	BASEMENT WALL  (IF APPLICABLE)	INSULATION (Uncond.)
н	stairs \$N1102.2.12 or \$NCECC 402.2.12	
	Home meets the Simulated Performance Alternative (PERFORMANCE OPTION)	1 (§NCECC 403.2.2) 5,4 SYSTEM 2 (§NCECC 403.2.2) 2 //
п	(IF APPLICABLE)	(IF APPLICABLE)  SYSTEM 3 (§NCECC 403.2.2)
	renestration*	TOTAL DUCT LEAKAGE
	SOLAR HEAT GAIN (SHGC)	TESTER TIFOLIE
81	ELECTRICAL & LIGHTING SYSTEMS	TESTING COMPANY SOUTHERN ENERGY MANAGEMENT
	Visually inspected according to \$N1104 or	PHONE (919) 836-0330
1	SNCECC 404 (75%+ high-efficiency lighting)	TESTING DATE
	Values listed indicate pre	dominant rating found in home  Rev. 6

Page 72 of 217 Report Created: 03/27/2025




Page 73 of 217 Report Created: 03/27/2025

Electrical Equipment / MEP showing PV Tie in (Up close)




Page 74 of 217 Report Created: 03/27/2025


Electrical Equipment / MEP showing PV Tie in (Up close)




Page 75 of 217 Report Created: 03/27/2025



Page 76 of 217 Report Created: 03/27/2025



Page 77 of 217 Report Created: 03/27/2025



Page 78 of 217 Report Created: 03/27/2025

Electrical Equipment / MEP: Nameplate with busbar rating



Electrical Equipment / MEP: Nameplate with busbar rating



Loc: 35.884, -80.6768

Electrical Equipment / MEP: Nameplate with busbar rating



Loc: 35.884, -80.6768

Electrical Equipment / MEP: Nameplate with busbar rating



Loc: 35.884, -80.6768

Page 79 of 217 Report Created: 03/27/2025

### Electrical Equipment / Photo of all service panels




Loc: **35.8807**, **-80.6853** 

Electrical Equipment / Photo of all service panels



Loc: **35.8807**, **-80.6853** 

Electrical Equipment / Interconnection Point: Up Close



Loc: 35.8761, -80.6936


Electrical Equipment / Interconnection Point: Up Close



Loc: 35.8761, -80.6936

Page 80 of 217 Report Created: 03/27/2025

**Electrical Equipment / Interconnection Point: Up Close** 




Loc: 35.8761, -80.6936

Electrical Equipment / Interconnection Point: Up Close




Loc: 35.8761, -80.6936

**Electrical Equipment / Interconnection Point: Up Close** 



Loc: 35.8761, -80.6936

Electrical Equipment / Interconnection Point: Up Close



Loc: 35.8761, -80.6936


Page 81 of 217 Report Created: 03/27/2025

Electrical Equipment / Interconnection point: Pulled Back



Loc: **35.8736, -80.6976** 

Electrical Equipment / Interconnection point: Pulled Back



Loc: **35.8736, -80.6976** 

Page 82 of 217 Report Created: 03/27/2025

Electrical Equipment / PV Label/Sticker at Main Electrical Panel (PV5-Label 2,3, 7 & 8)



Loc: **35.8713, -80.7025** 

Page 83 of 217 Report Created: 03/27/2025

Electrical Equipment / PV Label/Sticker at Main Electrical Panel (PV5-Label 2,3, 7 & 8)



Loc: **35.8713, -80.7025** 

Page 84 of 217 Report Created: 03/27/2025

Electrical Equipment / PV Label/Sticker at Main Electrical Panel (PV5-Label 2,3, 7 & 8)



Loc: **35.8713, -80.7025** 

Page 85 of 217 Report Created: 03/27/2025

Electrical Equipment / Sealing of LB above 8ft



Loc: 35.8698, -80.7089

Electrical Equipment / Sealing of LB above 8ft



Loc: 35.8698, -80.7089

 $\textbf{Electrical Equipment} \ / \ \textbf{Sealing of LBs, LLs, and LRs at mounted equipment}$ 



Loc: **35.8693**, **-80.7195** 

Electrical Equipment / Sealing of LBs, LLs, and LRs at mounted equipment



Loc: **35.8693**, **-80.7195** 

Page 86 of 217 Report Created: 03/27/2025

Electrical Equipment / Sealing of LBs, LLs, and LRs at mounted equipment



Loc: **35.8693, -80.7195** 

Page 87 of 217 Report Created: 03/27/2025

Electrical Equipment / Utiltiy Meter showing account number with address card



Loc: **35.8667, -80.7327** 

Page 88 of 217 Report Created: 03/27/2025

Electrical Equipment / Utiltiy Meter showing account number with address card



Loc: **35.8667, -80.7327** 

Page 89 of 217 Report Created: 03/27/2025

Electrical Equipment / PV Label/Sticker at Utility Meter (PV5-Label 9)



Loc: **35.862, -80.7397** 

Page 90 of 217 Report Created: 03/27/2025



Loc: **35.862, -80.7397** 

Page 91 of 217 Report Created: 03/27/2025

### **Electrical Equipment / Ground Rod**



Loc: 35.8577, -80.7461

Electrical Equipment / Ground Rod



Loc: 35.8577, -80.7461

**Electrical Equipment / Ground wire** 



Loc: 35.8539, -80.7518

Electrical Equipment / Ground wire



Loc: 35.8539, -80.7518

Page 92 of 217 Report Created: 03/27/2025

### Electrical Equipment / Ground wire



Loc: 35.8539, -80.7518

### Electrical Equipment / Ground wire



Loc: **35.8539, -80.7518** 


Page 93 of 217 Report Created: 03/27/2025

Electrical Equipment / Ground wire/rod pic from 6t back showing both



Page 94 of 217 Report Created: 03/27/2025

Electrical Equipment / Ground wire/rod pic from 6t back showing both



Page 95 of 217 Report Created: 03/27/2025


**Electrical Equipment / Monitoring Device serial number** 



Loc: **35.842, -80.7775** 

Page 96 of 217 Report Created: 03/27/2025

### **Electrical Equipment / Commission Complete/ Monitoring**



## **Electrical Equipment / Commission Complete/ Monitoring**



#### **Electrical Equipment / Commission Complete/ Monitoring**




### **Electrical Equipment / Commission Complete/ Monitoring**




Page 97 of 217 Report Created: 03/27/2025


### Electrical Equipment / Commission Complete/ Monitoring



### Electrical Equipment / Commission Complete/ Monitoring



#### **Electrical Equipment / Commission Complete/ Monitoring**




### **Electrical Equipment / Commission Complete/ Monitoring**



Page 98 of 217 Report Created: 03/27/2025


### Electrical Equipment / Commission Complete/ Monitoring




#### Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting



# Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting



# Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting



Page 99 of 217 Report Created: 03/27/2025


# Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting




# Electrical Equipment / Commission Complete: screenshot of all strings/micros/optis reporting



# Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting




## Electrical Equipment / Commission Complete: screenshot of all strings/micros/optis reporting



Page 100 of 217 Report Created: 03/27/2025

Electrical Equipment / Commission Complete: screenshot of all strings/ micros/optis reporting



Roof / Rail Mounts (close up)



Roof / Rail Mounts (close up)



Roof / Sealing around L feet



Loc: 35.3135, -79.0888

Page 101 of 217 Report Created: 03/27/2025

Roof / Sealing around L feet



Page 102 of 217 Report Created: 03/27/2025

Roof / Measurement between mounted L-feet



Loc: **35.302, -79.0842** 


Page 103 of 217 Report Created: 03/27/2025

Roof / Measurement between mounted L-feet




Loc: **35.302, -79.0842** 

Page 104 of 217 Report Created: 03/27/2025




Page 105 of 217 Report Created: 03/27/2025



Page 106 of 217 Report Created: 03/27/2025

## Roof / Rail Mounts - Roof Run




Loc: **35.2891, -79.0771** 

Roof / Rail Mounts - Roof Run



Loc: 35.2891, -79.0771

Roof / Rail Mounts - Roof Run



Loc: **35.2891, -79.0771** 

Roof / Rail Mounts - Roof Run



Loc: **35.2891, -79.0771** 

Page 107 of 217 Report Created: 03/27/2025

Roof / Rail Mounts - Roof Run





Roof / Rail Mounts - Roof Run



Roof / Rail Mounts - Roof Run



Report Created: 03/27/2025 Page 108 of 217

Roof / Rail Mounts - Roof Run



Roof / Rail Mounts - Roof Run



Page 109 of 217 Report Created: 03/27/2025



Page 110 of 217 Report Created: 03/27/2025



Page 111 of 217 Report Created: 03/27/2025



Page 112 of 217 Report Created: 03/27/2025



Page 113 of 217 Report Created: 03/27/2025



Page 114 of 217 Report Created: 03/27/2025



Page 115 of 217 Report Created: 03/27/2025



Page 116 of 217 Report Created: 03/27/2025



Page 117 of 217 Report Created: 03/27/2025



Page 118 of 217 Report Created: 03/27/2025



Page 119 of 217 Report Created: 03/27/2025

Roof / Rail Pictures - 5-6 photos



Loc: **35.2793**, **-79.073** 

Roof / Rail Pictures - 5-6 photos



Loc: **35.2793**, **-79.073** 

Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Loc: **35.2793**, **-79.073** Loc: **35.2793**, **-79.073** 

Page 120 of 217 Report Created: 03/27/2025

## Roof / Rail Pictures - 5-6 photos



Loc: 35.2793, -79.073

Roof / Rail Pictures - 5-6 photos



Loc: 35.2793, -79.073

Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Page 121 of 217 Report Created: 03/27/2025

Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Page 122 of 217 Report Created: 03/27/2025

Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos



Roof / Rail Pictures - 5-6 photos




Roof / Rail Pictures - 5-6 photos



Page 123 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)




Page 124 of 217 Report Created: 03/27/2025



Page 125 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)




Page 126 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)




Page 127 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)



Page 128 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)



Page 129 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)




Page 130 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)



Page 131 of 217 Report Created: 03/27/2025

Roof / Grounding Lug on Roof (upclose)



Page 132 of 217 Report Created: 03/27/2025



Page 133 of 217 Report Created: 03/27/2025

Roof / Grounding Connection between rails at each array



Loc: 35.2702, -79.061

Roof / Grounding Connection between rails at each array



Roof / Grounding Connection between rails at each array




Roof / Grounding Connection between rails at each array



Page 134 of 217 Report Created: 03/27/2025


Roof / Grounding Connection between rails at each array



Roof / Grounding Connection between rails at each array



Roof / Grounding Connection between rails at each array



Roof / Grounding Connection between rails at each array



Page 135 of 217 Report Created: 03/27/2025


Roof / Grounding Connection between rails at each array




Roof / Grounding Connection between rails at each array



Page 136 of 217 Report Created: 03/27/2025



Roof / SolaDeck - Not installed (with manufacture label showing and landmark)



 Page 138 of 217
 Report Created: 03/27/2025

Roof / SolaDeck - Not installed (with manufacture label showing and landmark)



Page 139 of 217 Report Created: 03/27/2025

Roof / SolaDeck - Not installed (with manufacture label showing and landmark)




Page 140 of 217 Report Created: 03/27/2025

Roof / Soladeck w/ Cx name and address (at each array)



Loc: **35.2613, -79.0472** 

Page 141 of 217 Report Created: 03/27/2025




Page 142 of 217 Report Created: 03/27/2025

Roof / Soladeck w/ Cx name and address (at each array)





Page 143 of 217 Report Created: 03/27/2025

Roof / Duct seal in soladeck



Loc: 35.2611, -79.0466





Loc: **35.2611, -79.0466** 

Roof / Duct seal in soladeck



Roof / Duct seal in soladeck



Page 144 of 217 Report Created: 03/27/2025

Roof / Soladeck showing all wiring connections



Loc: **35.258, -79.04** 

Roof / Soladeck showing all wiring connections



Loc: 35.258, -79.04

Roof / Soladeck showing all wiring connections




Loc: 35.258, -79.04

Roof / Soladeck showing all wiring connections



Roof / Soladeck showing all wiring connections





Roof / Soladeck showing all wiring connections



Roof / Soladeck showing all wiring connections



Page 146 of 217 Report Created: 03/27/2025

Roof / Soladeck showing all wiring connections





Roof / Soladeck with Lid On



Loc: **35.2545, -79.0331** 

Roof / Soladeck with Lid On




Loc: **35.2545**, **-79.0331** 

Page 147 of 217 Report Created: 03/27/2025


Roof / Soladeck with Lid On



Page 148 of 217 Report Created: 03/27/2025




Page 149 of 217 Report Created: 03/27/2025




Page 150 of 217 Report Created: 03/27/2025




Page 151 of 217 Report Created: 03/27/2025



Page 152 of 217 Report Created: 03/27/2025



Page 153 of 217 Report Created: 03/27/2025



Page 154 of 217 Report Created: 03/27/2025

## Roof / Roof Wiring at Rail



Loc: **35.252, -79.028** 

Roof / Roof Wiring at Rail



Loc: **35.252, -79.028** 

Roof / Roof Wiring at Rail



Loc: 35.252, -79.028

Roof / Roof Wiring at Rail



Loc: 35.252, -79.028

Page 155 of 217 Report Created: 03/27/2025

Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail




Loc: **35.252**, **-79.028** 

Roof / Roof Wiring at Rail



Loc: **35.252**, **-79.028** 

Roof / Roof Wiring at Rail



Loc: 35.252, -79.028

Page 156 of 217 Report Created: 03/27/2025

Roof / Roof Wiring at Rail




Loc: **35.252, -79.028** 

Roof / Roof Wiring at Rail




Loc: **35.252, -79.028** 

Roof / Roof Wiring at Rail



Loc: **35.252, -79.028** 

Roof / Roof Wiring at Rail




Loc: 35.252, -79.028

Page 157 of 217 Report Created: 03/27/2025

Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail





Roof / Roof Wiring at Rail



Page 158 of 217 Report Created: 03/27/2025

Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail



Page 159 of 217 Report Created: 03/27/2025


Roof / Roof Wiring at Rail




Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail




Report Created: 03/27/2025 Page 160 of 217

Roof / Roof Wiring at Rail



Roof / Roof Wiring at Rail





Roof / Wire Runs on roof



Loc: **35.2437**, **-79.0225** 

Page 161 of 217 Report Created: 03/27/2025

Roof / Wire Runs on roof



Loc: **35.2437**, **-79.0225** 

Roof / Wire Runs on roof



Loc: 35.2437, -79.0225

Roof / Wire Runs on roof



Loc: **35.2437**, **-79.0225** 


Roof / Wire Runs on roof



Loc: 35.2437, -79.0225


Page 162 of 217 Report Created: 03/27/2025

## Roof / Wire Runs on roof



Loc: **35.2437, -79.0225** 

Roof / Wire Runs on roof



Loc: **35.2437, -79.0225** 

Roof / Wire Runs on roof



Roof / Wire Runs on roof



Loc: **35.2437, -79.0225** 

Loc: 35.2437, -79.0225

Page 163 of 217 Report Created: 03/27/2025

## Roof / Wire Runs on roof



Roof / Wire Runs on roof



Loc: **35.2437, -79.0225** 


Loc: **35.2437, -79.0225** 

Roof / Wire Runs on roof



Loc: 35.2437, -79.0225

Roof / Wire Runs on roof




Page 164 of 217 Report Created: 03/27/2025


Roof / Wire Runs on roof



Roof / Wire Runs on roof



Roof / Wire Runs on roof



Roof / Wire Runs on roof



Page 165 of 217 Report Created: 03/27/2025

Roof / Wire Runs on roof



Roof / Wire Runs on roof



Roof / Wire Runs on roof



Roof / Wire Runs on roof



Page 166 of 217 Report Created: 03/27/2025


Roof / Wire Runs on roof



Page 167 of 217 Report Created: 03/27/2025



Page 168 of 217 Report Created: 03/27/2025




Page 169 of 217 Report Created: 03/27/2025



Page 170 of 217 Report Created: 03/27/2025



Page 171 of 217 Report Created: 03/27/2025



Page 172 of 217 Report Created: 03/27/2025




Page 173 of 217 Report Created: 03/27/2025



Page 174 of 217 Report Created: 03/27/2025




Page 175 of 217 Report Created: 03/27/2025



Page 176 of 217 Report Created: 03/27/2025



Page 177 of 217 Report Created: 03/27/2025



Page 178 of 217 Report Created: 03/27/2025



Loc: **35.2324, -79.018** 

Page 179 of 217 Report Created: 03/27/2025



Loc: **35.2324, -79.018** 


Page 180 of 217 Report Created: 03/27/2025

Roof / Rapid Shut Downs - Up close, installed



Loc: **35.2324, -79.018** 

Page 181 of 217 Report Created: 03/27/2025



Loc: **35.2324, -79.018** 

Page 182 of 217 Report Created: 03/27/2025

Roof / Rapid Shut Downs - Up close, installed




Page 183 of 217 Report Created: 03/27/2025

Roof / Rapid Shut Downs - Up close, installed



Page 184 of 217 Report Created: 03/27/2025



Page 185 of 217 Report Created: 03/27/2025

Roof / Rapid Shut Downs - Up close, installed



Page 186 of 217 Report Created: 03/27/2025

Roof / Mids - Installed (Up close)



Roof / Mids - Installed (Up close)



Roof / Mids - Installed (Up close)



Page 187 of 217 Report Created: 03/27/2025



Page 188 of 217 Report Created: 03/27/2025




Page 189 of 217 Report Created: 03/27/2025

Roof / Ends/camo - Installed (Up close)




Page 190 of 217 Report Created: 03/27/2025

Roof / Ends/camo - Installed (Up close)




Page 191 of 217 Report Created: 03/27/2025

Roof / Measurement from roof to the bottom of the panel (4")




Page 192 of 217 Report Created: 03/27/2025

Roof / Measurement from roof to the bottom of the panel (4")



Page 193 of 217 Report Created: 03/27/2025

Roof / Measurement from roof to the bottom of the panel (4")




Page 194 of 217 Report Created: 03/27/2025



Page 195 of 217 Report Created: 03/27/2025




Page 196 of 217 Report Created: 03/27/2025




Page 197 of 217 Report Created: 03/27/2025

Roof / Photo of wire management under array after panels are laid.




Page 198 of 217 Report Created: 03/27/2025


Roof / Photo of wire management under array after panels are laid.



Page 199 of 217 Report Created: 03/27/2025




Page 200 of 217 Report Created: 03/27/2025




Page 201 of 217 Report Created: 03/27/2025



Page 202 of 217 Report Created: 03/27/2025




Page 203 of 217 Report Created: 03/27/2025



Page 204 of 217 Report Created: 03/27/2025




Page 205 of 217 Report Created: 03/27/2025




Page 206 of 217 Report Created: 03/27/2025

Roof / Photo of wire management under array after panels are laid.




Page 207 of 217 Report Created: 03/27/2025




Page 208 of 217 Report Created: 03/27/2025

Roof / Photo of wire management under array after panels are laid.




Page 209 of 217 Report Created: 03/27/2025


Roof / Photo of wire management under array after panels are laid.




Page 210 of 217 Report Created: 03/27/2025




Page 211 of 217 Report Created: 03/27/2025




Page 212 of 217 Report Created: 03/27/2025



Page 213 of 217 Report Created: 03/27/2025



Page 214 of 217 Report Created: 03/27/2025



Page 215 of 217 Report Created: 03/27/2025

## Roof / Roof penetration



Loc: **35.224, -79.0082** 

Roof / Roof penetration



Roof / Roof penetration



Loc: **35.224, -79.0082** 

Roof / Tilt Meter: On Glass



Page 216 of 217 Report Created: 03/27/2025

Roof / Tilt Meter: On Glass





Roof / Tilt Meter: On Roof



Page 217 of 217 Report Created: 03/27/2025