

Installer: NC Solar Now Customer: Capel, Lorenzo

Subject: PV System Post Installation Inspection

To whom it may concern:

Model Energy, PLLC performed a field inspection on **6/9/25**, to the property located **323 Winterberry Way**, **Fuquay-Varina**, **NC 27526** and has reviewed the installation details of the PV system that was installed by NC Solar Now. The field inspection was performed by myself, Andrew King (a North Carolina registered design professional), or a person under my direct supervisory control. The review was limited to the structural elements involved in the construction.

This post installation field inspection of the PV system verifies:

- 1) The PV equipment's structural installation has been designed and inspected
- 2) The equipment will not create a negative impact on the building's structural design, including any additional loads imposed (dead, wind, snow)
- 3) The installation is in compliance with the 2018 North Carolina Residential Code

Thank you,

Andrew King, PE