


FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948									
LONG TERM ACCEPTANCE RATE	.1955									



- ① stake
- ① rock to 18" had digger
- ② rock to 12"
- ③ 0-18 rock 18-20 sec/pc
R/SP?
- ④ 0-36 w/sic (?)
①8 mottled 30"
- ⑤ 0-36 w/sic
①8
- ⑥ 0-16 w/sic 16-24 sec Heavy/Weak
- ⑦ 0-36 w/sic wet to top of 28"
①8
- ⑧ needs hundreds remove - leave trees for layout