


APPLICANT NAME _____

DATE _____

FACTORS		PROCESSES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-34	0-18	0-18	0-18					
Texture Group	.1941(A)(1)	slc	slc	slc	slc					
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		24-42	18-26	18-38	18-36					
Texture Group	.1941(A)(1)	slc	slc	slc	slc					
Consistence	.1941	slc								
Structure	.1941(A)(2)	slc								
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH			26-38							
Texture Group	.1941(A)(1)		slc							
Consistence	.1941		Fd							
Structure	.1941(A)(2)		SBC							
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942		36"	36"	36"					
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948		P'	P'	P'					
LONG TERM ACCEPTANCE RATE	.1955	.6	.5	.4	.4					



contractor meet on site
 18" ditch prior to tank setting
 3 x 100' lines

