OPERATIONS PERMIT

Name: (owner) Robert M Clamb Property Location: SR# 2021	New Installation Septic Tank Repairs Nitrification Li
Subdivision	Lot #
Contractor: Fair cloth	Quadrant #
Basement with Plumbing: Garage:	
Water Supply: Well Public Community	
Distance From Well: 50 ft.	
Following are the specifications for the sewage disposal sys	tem on above captioned property.
Type of system: Conventional Other Poly	Styrene aggregate Trench
Size of tank: Septic Tank: Pu	mp Tank: gallons
Subsurface No. of exact length of each ditch	width of 3 depth of 24 in.
PERMIT NO. 7/55 Linear feet Date: 1 Inspected	by: Environmental Health Specialist
Tout Info 3/6/00 BJS-1000 SJE-1000 STE-103 Zabel filta *Maintain \$5 R SO well setted.	epair epair