ENT

Nº13932

## **OPERATIONS PERMIT**

Name: (owner) WILLAM ATKINS  Property Location: SR#/581 Bailey X RDS  Subdivision Seagure  TAX ID#	Repairs Nitrification Line  Lot #
Contractor:    Summer  Basement with Plumbing:	
Type of system: Conventional Other  Size of tank: Septic Tank: Ooo gallons Proceedings of each ditches of each	ump Tank: gallons width of depth of
Date:	3-13- 01  by: Same & Masher Specialist  Environmental Health Specialist
Repair 2 Bru- Home.	Greeley chapel chapel