

# OPERATIONS PERMIT

Name: (owner) DANNY WATKENS JR INC

New Installation  Septic Tank

Property Location: SR# 1553 Live Oak

Repairs  Nitrification Line

Subdivision Bram Tree Acres Lot # 3

TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Harold Chappell Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 50' ft.

### Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field: No. of ditches 3 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18-20 in.

French Drain: \_\_\_\_\_ Linear feet

Date: 9-26-00

PERMIT NO. 17147

Inspected by: James E. Manshart D.C.S.  
Environmental Health Specialist

