Nº 11097

1	VIRONMENTAL HEAL	TH SECT I	- 11097
0.400005/	OPERATIONS	PERMIT	
Name: (owner) — Property Location:	SR#_//20 Subdivision Whisper Crack	New Installation Repairs Lot # 36 Quadrant #	Septic Tank Nitrification Li
Contractor:	The Strichland	Registration #	
Basement with Plum	nbing: Garage:		
Water Supply:	Well Public Community		
Distance From Well	: 50 ft.		
Following are the s	pecifications for the sewage disposal sy	stem on above captioned pr	operty.
Type of system:	Conventional Septic Tank: Oco gallons P	styrene Aggregations ump Tank: gallons	Turk
Subsurface Drainage Field	No. of 2 exact length ditches of each ditch	width of depth ditches ft. ditche	//
French Drain:	Linear feet	17T 220	1
PERMIT NO.	Date: Inspected	by: Unchestal Health	
	LPP Repair 1 815	Polyhol BTS-10 STB-10	LINO ElHer 000 03