OPERATIONS PERMIT

Name: (owner) Septic Tank
Property Location: SR# 120 Repairs Nitrification Lin
Subdivision STON CROSS Lot #
TAX ID# Quadrant #
Contractor: C9M B. HANING & Backbee Registration # Registration # Scenice Garage: SYSTEM INTAINED AS BEST
Basement with Plumbing: Garage: SYSTEM INTAILED AS BEST
Water Supply: Well Public Community As Could be as Shown-
Distance From Well: 50 ft. As shown system would be going up hill at least steet
Following are the specifications for the sewage disposal system on above captioned property.
Type of system: Conventional Other
Size of tank: Septic Tank: gallons Pump Tank: gallons
Subsurface No. of 2 exact length of each ditch 75 ft. ditches 3 ft. depth of ditches in.
French Drain: Linear feet
Date: 03- 6-01
PERMIT NO. 17304 Date: 03- 6-01 Inspected by: 90 Walk Specialist
Environmental Health Specialist
mcp-box
F 78 -5 573-814
1-20-01
Rd //
25 / 45'
115'