


APPLICANT NAME \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-33	0-48	0-38	0-42	0-36				
Texture Group	.1941(A)(1)	US/C	US/S	US/L	US/S	US/S				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		33-42								
Texture Group	.1941(A)(1)	see ?								
Consistence	.1941	PM								
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942			40'	76"					
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948		S	S	S	S				
LONG TERM ACCEPTANCE RATE	.1955	?	.8	.8	.8	.8				



1 x 200' feet  
 on center  
 18-24" ditch depth  
 400' laid out  
 18" ditch depth  
 for repair