

SITE SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-21	0-20	0-21						
Texture Group	.1941(A)(1)	SL	SL	SL						
Consistence	.1941	VF	VF	VF						
Structure	.1941(A)(2)	G	G	G						
Mineralogy	.1941(A)(3)	NB	NB	NB						
HORIZON 2 DEPTH		30-75	34-75							
Texture Group	.1941(A)(1)	SL	SL							
Consistence	.1941	F	F							
Structure	.1941(A)(2)	SP	SP							
Mineralogy	.1941(A)(3)	SG	SG							
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	5	15	18						
LONG TERM ACCEPTANCE RATE	.1955	.8	.45	.5						

①

②

③

1

③

le

NCSR # 1521

"GREGORY CIRCLE"

PKN CL ROAD & CULVERT

①

DANIEL J. THOMAS
DB 962, PG 736
PC D, SLIDE 66-D

PKN

EIS

PKN

NIS

NIS

2.01 AC.

Proposed
SFD

Proposed
Septic
tank

SITE PLAN APPROVAL

DISTRICT RA 30 USE SFD

#BEDROOMS 3

8-3-00 [Signature]

Date Zoning Administrator

Required Property Line Setbacks

	Minimum	Actual
Front	<u>35</u>	<u>133</u>
Side	<u>10</u>	<u>40</u>
Corner	<u>25</u>	<u>63</u>
Rear	<u>10</u>	<u>—</u>
Nearest Building	<u>—</u>	<u>—</u>

MARY PEARL MITCHELL ENNIS
AND HERBERT H. ENNIS
DB 388, PG 117

MARY PEARL MITCHELL ENNIS
AND HERBERT H. ENNIS
DB 388, PG 117

NIS