

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

TE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-16	6-16	0-19											
Texture Group	.1941(A)(1)	USL	USL	USL											
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		16-38	16-36	19-36											
Texture Group	.1941(A)(1)	SCL	SCL	SCL											
Consistence	.1941	Fv/Ss	Fv/Fv	Fv/Ss											
Structure	.1941(A)(2)	Gr/Ss	Ss/Ss	Ss											
Mineralogy	.1941(A)(3)	Ss/Ss	Ss/Ss	Ss											
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	—	—	—											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	ps	ps	ps											
LONG TERM ACCEPTANCE RATE	.1955	.6	.5	.5											

- 3 x 80 lines  
 - 18" - 24" deep  
 LPP Repair

SITE PLAN APPROVAL

DISTRICT N/A USE SFD


#BEDROOMS 3

Date 12-10-99

*Alexa Byrd*

Zoning Administrator

*Montana Lane 60'R/W*



*Plot Plan*  
**Price Construction Company**

*Sierra Villa Subdivision Section Nine*  
*PC # F Slide 266-B*

*Anderson Creek*