

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

PROFILE EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940	L	L	L						
SLOPE (%)	.1940	Z	Z	Z						
HORIZON 1 DEPTH		0-12								
Texture Group	.1941(A)(1)	SL								
Consistence	.1941	FL								
Structure	.1941(A)(2)	GR								
Mineralogy	.1941(A)(3)	NSNP								
HORIZON 2 DEPTH		12-18								
Texture Group	.1941(A)(1)	SCL								
Consistence	.1941	FL								
Structure	.1941(A)(2)	GR								
Mineralogy	.1941(A)(3)	SSSP								
HORIZON 3 DEPTH		18-36								
Texture Group	.1941(A)(1)	SC-CL								
Consistence	.1941	FL								
Structure	.1941(A)(2)	SBC								
Mineralogy	.1941(A)(3)	SSSP								
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	32	34	36						
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	P5	P5	P5						
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4						