


APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-6	6-0	8-8	12-0	12-0				
Texture Group	.1941(A)(1)	sl	fill	fill	fill	fill				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		0-36	0-16	8-20	0-36	0-30				
Texture Group	.1941(A)(1)	c	sl	sl	sl	sl				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH			16-36	20-36		30-36				
Texture Group	.1941(A)(1)		c	c		sl				
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/.1956									
CLASSIFICATION	.1948									
LONG TERM ACCEPTANCE RATE	.1955	.3	.3	.3	.16	.5				

2



1x200  
62  
24" nest on site

Rd

Rd