

# OPERATIONS PERMIT

Name: (owner) Paulene Stinson  New Installation  Septic Tank  
 Property Location: SR# 1147 Rainey Dr  Repairs  Nitrification Line  
 Subdivision Twin Lakes Lot # 10  
 TAX ID# \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: Ottis Strickland Registration # \_\_\_\_\_


Basement with Plumbing:  Garage:   
 Water Supply:  Well  Public  Community  
 Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other Pump to Comu.  
 Size of tank: Septic Tank: 1000 gallons Pump Tank: 1000 gallons  
 Subsurface Drainage Field No. of ditches 3 exact length of each ditch 70 ft. width of ditches 3 ft. depth of ditches 18 in.  
 French Drain: \_\_\_\_\_ Linear feet

PERMIT NO. 16674  
Com. Repair

Date: 04-05-00  
 Inspected by: Vernon Dodge  
 Environmental Health Specialist



\* Home not on-site  
 \* Polylok filter  
 Tank Info  
 \* BTS-1000  
 STB-103  
 2/10/00