

Hugh Beasley's Heating & Air, Inc.
 57 WC Beasley Lane
 Coats, NC 27521
 919-894-4248

**HVAC
 SERVICE ORDER
 INVOICE
 No. 60852**

Beasleyshvac@Aoi.Com

Paul
 Lock box
 201

BILL TO Danny West
9 E. Main St.
Dannie - 910-890-3660
Smith

THIS WORK IS TO BE
 C.O.D. CHARGE NO CHARGE

MAKE Nordyne MAKE
 MODEL GB3BM-024KA05B MODEL
 SERIAL NUMBER GBD050409831 SERIAL NUMBER

NAME COACHS office
 STREET 8105b
 CITY
 PHONE
 TECHNICIAN
 WORK TO BE PERFORMED ATS Unit drain pan

ENVIRONMENTAL CHECK LIST			WORK PERFORMED	
WORK PERFORMED	QTY.	TYPE/DISPOSITION	CONDENSING UNIT	COND'S/ATE DRAINS
<input type="checkbox"/> RECOVERED			LEVELED	CLEANED MAIN DRAIN
<input type="checkbox"/> RECYCLED			CLEANED COIL	REPAIRED MAIN DRAIN
<input type="checkbox"/> RECLAIMED			CHECKED CHARGE	CLEANED PAN DRAIN
<input type="checkbox"/> RETURNED			REPAIRED LEAK IN COIL	REPAIRED PAN DRAIN
<input type="checkbox"/> DISPOSAL			REPAIRED LEAK IN COPPER	FURN. OR FAN COIL
<input type="checkbox"/> DISEMPOWERED			* REF.	REPLACED BELT
<input type="checkbox"/> CHANGED OUT/REPLACED		TOTAL \$	CHECKED MOTOR	ADJUSTED BELT
			CHANGED MOTOR	REPLACED PULLEY
			REPLACED BELT	ADJUSTED PULLEY
			ADJUSTED BELT	CLEANED BLOWER
			REPLACED CONTACTOR	REPLACED BEARINGS
			REPL. START. RELAY	OILED MOTOR
			REPL. START. CAPACITOR	OILED BEARINGS
			REPLACED RUN CAPACITOR	CLEANED HEAT EXCH.
			CLEANED OR ADJ. CONTACTOR	REPLACED HEAT EXCH.
			REPAIRED WIRING	CLEANED OR ADJ. PILOT
			REPLACED FUSE	REPLACED THERMOCOUPLE
			REPLACED COMPRESSOR	REPAIRED VALVE
			EVAPORATOR COIL	REPLACED VALVE
			REPLACED EXP. VALVE	CLEANED BURNERS
			ADJUSTED EXP. VALVE	DUCT
			REPLACED CAP TUBE	REPAIRED
			CLEANED CAP TUBE	ADJUSTED
			REPAIRED COIL LEAK	THERMOCSTAT
			REPAIRED COPPER CORN.	REPLACED
			CLEANED COIL	ADJUSTED
			LEVELED COIL	
			ELECT. HTR.	CLB TOWER
			REPLACED LINK	CLEANED
			REPLACED KUX	
			REPAIRED WIRE	FUMPS(S)
			REPLACED CONT.	GREASED
				REPAIRED

QTY.	MATERIALS & SERVICES	UNIT PRICE	AMOUNT
	REFRIGERANT R-22 ^{LBS}		
	A 275.58		
	FILTERS x x		
	FILTERS x x		
	BELTS		
TOTAL MATERIALS			

HRS.	LABOR	RATE	AMOUNT
1	Kyle		
TOTAL LABOR			

TERMS

MATERIALS & LABOR MAY BE CONTINUED ON OTHER SIDE

I have authority to order the work outlined above which has been satisfactorily completed. I agree that Seller retains title to equipment/materials furnished until final payment is made. If payment is not made as agreed, seller can remove said equipment/materials at Seller's expense. Any damage resulting from said removal shall not be the responsibility of Seller.

CUSTOMER SIGNATURE _____ DATE _____

RECOMMENDATIONS

REGULAR WARRANTY

SERVICE CONTRACT

Thank You

TOTAL SUMMARY	
TOTAL MATERIALS	
TOTAL LABOR	
TRAVEL CHARGE	
TAX	
TOTAL	

Lillington
North Carolina 27546

- ↑ 1. Head west toward S Main St
1 s (43 ft)

Take US-421 S/US Hwy 421 S to Leslie Campbell Ave

7 min (4.8 mi)

- ↪ 2. Turn right onto S Main St
1.5 mi
- ↪ 3. Turn right onto US-421 S/US Hwy 421 S
3.3 mi

Continue on Leslie Campbell Ave. Take NC-27 E to E Main St in Coats

8 min (4.7 mi)

- ↶ 4. Turn left onto Leslie Campbell Ave
0.4 mi
- ⦿ 5. At the traffic circle, take the 2nd exit and stay on Leslie Campbell Ave
0.2 mi
- ⦿ 6. At the traffic circle, continue straight
302 ft
- ↗ 7. Continue onto Leslie Campbell Ave
1.4 mi
- ⤴ 8. Merge onto NC-27 E
2.4 mi
- ↪ 9. Turn right onto N McKinley St
0.3 mi
- ↶ 10. Turn left onto E Main St
 - 📍 Destination will be on the left
 69 ft

9 E Main St
Coats, NC 27521