


APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILE													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-20	0-36	0-22	0-20	0-42	0-42	0-86	0-30						
Texture Group	.1941(A)(1)	LS/SL	LS/SL	LS/SL	LS/SL	SL	SL	SL	SL						
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		20-34	36-42	22-30	20-26					20-42					
Texture Group	.1941(A)(1)	LS/SL	SCL	SCL	SCL/SC					SCL					
Consistence	.1941	Fi/Fr	Fr	Fi	Fi					Fr					
Structure	.1941(A)(2)	SBC	SBC	SBC	SBC					SBC					
Mineralogy	.1941(A)(3)	SEXP	SEXP	SEXP	EXP					SEXP					
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	34"	—	28"	24"										
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/1956														
CLASSIFICATION	.1948		PS	PS	?										
LONG TERM ACCEPTANCE RATE	.1955		.6	(5/4)?	?	.8	.8	.8	.4						



4 x 75' Area  
 18-24 ditches  
 on contour