

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

D₁

| FACTORS | | PROFILES | | | | | | | | | |
|---------------------------|-------------|----------|--------|------|--------|-------|-------|------|-------|---|----|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-8 | 0-10 | 0-8" | 0-10" | 0-30" | 0-30" | 0-36 | 0-30 | | |
| Texture Group | .1941(A)(1) | SL | SL | SL | SL | LS | LS | LS | LS | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 2 DEPTH | | 8-12 | 10-31" | 8" | 10-30" | 30" | 32" | | 30-36 | | |
| Texture Group | .1941(A)(1) | SM | SCL | SCL | SCL | SCL | SCL | | SL | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 3 DEPTH | | | 31" | | | | | | | | |
| Texture Group | .1941(A)(1) | | SM/SL | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | 2" | | 8" | 24" | | | 30" | 32" | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | US | PS | US | PS | PS | PS | PS | PS | | |
| LONG TERM ACCEPTANCE RATE | .1955 | | | | | .4 | .4 | .8 | .6 | | |

3x100 @ 18"

