

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME \_\_\_\_\_

D \_\_\_\_\_

| FACTORS                   |             | PROFILES |   |   |   |   |   |   |   |   |    |  |  |  |
|---------------------------|-------------|----------|---|---|---|---|---|---|---|---|----|--|--|--|
|                           |             | 1        | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |  |  |  |
| LANDSCAPE POSITION        | .1940       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SLOPE (%)                 | .1940       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 1 DEPTH           |             | 0.14     |   |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) | u        |   |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 2 DEPTH           |             | 18.30    |   |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) | SL       |   |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 3 DEPTH           |             | 3.30     |   |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) | SL       |   |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| HORIZON 4 DEPTH           |             |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Texture Group             | .1941(A)(1) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Consistence               | .1941       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Structure                 | .1941(A)(2) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| Mineralogy                | .1941(A)(3) |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SOIL WETNESS              | .1942       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| RESTRICTIVE HORIZON       | .1944       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| SAPROLITE                 | .1943/.1956 |          |   |   |   |   |   |   |   |   |    |  |  |  |
| CLASSIFICATION            | .1948       |          |   |   |   |   |   |   |   |   |    |  |  |  |
| LONG TERM ACCEPTANCE RATE | .1955       | —————    |   |   |   |   |   |   |   |   |    |  |  |  |

1/4/00

*Part of*



THOMAS  
565/109

SITE PLAN APPROVAL

DISTRICT RAZOR USE

#BEDROOMS 2.3

3-1103

Zoning Administrator

*Triptew*  
*J. Brock*

*J. Brock*

565/112229