

03-5-7037

OPERATIONS PERMIT

Name: (owner) MUNDY, JACOB New Installation Septic Tank
 Property Location: SR# 1201 PONDEROSA RD Repairs Nitrification Line
 Subdivision MORLEY FARM Lot # 2
 TAX ID# _____ Quadrant # _____
 Contractor: LARRY SHARPE Registration # _____

Basement with Plumbing: Garage:
 Water Supply: Well Public Community
 Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____
 Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons
 Subsurface Drainage Field No. of ditches 1 exact length of each ditch 360 ft. width of ditches 3 ft. depth of ditches 18 in.
 French Drain: 300 Linear feet

Date: 9/22/03

PERMIT NO. 19412 SR 1201 Inspected by: [Signature] Environmental Health Specialist

