

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-16	0-18	0-16	0-14									
Texture Group	.1941(A)(1)	LS	LS	LS	LS									
Consistence	.1941	UFR	UFR	UFR	UFR									
Structure	.1941(A)(2)	G	G	G	G									
Mineralogy	.1941(A)(3)	NeH	NeH	NeH	NeH									
HORIZON 2 DEPTH		16-30	18-28	16-30	14-30									
Texture Group	.1941(A)(1)	Sc1	Sc1	Sc1	Sc1									
Consistence	.1941	F	F	F	F									
Structure	.1941(A)(2)	Sbk	Sbk	Sbk	Sbk									
Mineralogy	.1941(A)(3)	SoH	SoH	SoH	SoH									
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942	26"	24"	25"	26"									
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	US/PS	US/PS	US/PS	US/PS									
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4	.4									

