

SITE/ SOIL EVALUATION FOR ON- SITE WASTEWATER

APPLICANT NAME _____

DATE _____

| FACTORS | | PROFILES | | | | | | | | | |
|---------------------------|-------------|----------|-------|-------|--------|--------|--------|---|---|---|----|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-32 | 0-10 | 0-8 | 0-12" | 0-12' | 0-10' | | | | |
| Texture Group | .1941(A)(1) | SL | SL | SL | SL | SL | SL | | | | |
| Consistence | .1941 | VFR | VFR | VFR | VFR | VFR | VFR | | | | |
| Structure | .1941(A)(2) | G | G | G | G | G | G | | | | |
| Mineralogy | .1941(A)(3) | NS/NP | NS/NP | NS/NP | NS/NP | NS/NP | NS/NP | | | | |
| HORIZON 2 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| HORIZON 3 DEPTH | | 32" | 10" | 8" | 12-40" | 12-40" | 12-40" | | | | |
| Texture Group | .1941(A)(1) | SCL | SC | SC | SCL | SCL | SCL | | | | |
| Consistence | .1941 | FR | F | F | FR | FR | FR | | | | |
| Structure | .1941(A)(2) | SBK | SBK | SBK/M | SBK | SBK | SBK | | | | |
| Mineralogy | .1941(A)(3) | SS/SP | S/P | S/P | SS/NP | SS/NP | SS/NP | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| Texture Group | .1941(A)(1) | | | | | | | | | | |
| Consistence | .1941 | | | | | | | | | | |
| Structure | .1941(A)(2) | | | | | | | | | | |
| Mineralogy | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | 36" | 20" | 20" | 36" | 36" | 36" | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | P3 | P3 | P3 | P3 | P3 | P3 | | | | |
| LONG TERM ACCEPTANCE RATE | .1955 | .6 | .3 | | .6 | .6 | .6 | | | | |

4x50' @ 12-24"

