

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-12	0-16"	0-12"										
Texture Group	.1941(A)(1)	LS	LS	LS										
Consistence	.1941	VFR	VFR	VFR										
Structure	.1941(A)(2)	G	G	G										
Mineralogy	.1941(A)(3)	NS/NP	NS/NP	NS/NP										
HORIZON 2 DEPTH		12"	16-38"	12"										
Texture Group	.1941(A)(1)	SC2	SC2	SC2										
Consistence	.1941	FR	FR	FR										
Structure	.1941(A)(2)	SBK	SBK	SBK										
Mineralogy	.1941(A)(3)	S/P	S/P	S/P										
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942													
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS	PS	PS										
LONG TERM ACCEPTANCE RATE	.1955	.4	.4	.4										

4x100 @ 18"-24"  
LPP REPAIR



