03-5-7826 REPAIR

OPERATIONS PERMIT

Name: (owner) LIBBY HENDRIX		New Installation	Septic Tank
Property Location: SR# 1505 PEARIOGE Ro		Repairs	Nitrification Lin
Subdivision		Lot #	_
TAX ID#		Quadrant #	
Contractor: HAL BROWN		Registration #	
Basement with Plumbing:	Garage:		
Water Supply:	ublic		
Distance From Well: 50	ft.		
Following are the specifications for	or the sewage disposal sys	tem on above captione	ed property.
Tune of system: M.Conventional	C) Other		
Type of system: Conventional			
	gallons Pu	_	llons
Subsurface No. of Drainage Field ditches 5	exact length of each ditch	width of d ditches 3 ft. d	
French Drain: Lin	near feet		
	Date:	H7/04	
PERMIT NO. 20719	Inspected	by:	AS.
	52 1505 810	Environmental F	lealth Specialist
	DR-VE		
	24xST	EXIST HOUSE	