

HTE 04-5-9097

HAMILTON COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

16870

OPERATIONS PERMIT

Name: (owner) Joseph E. Stambaugh Jr.

New Installation Septic Tank

Property Location: SR# Sugar Hill Rd.

Repairs Nitrification Line

Subdivision Weswood IV

Lot # 30

Tax ID # _____

Quadrant # _____

Contractor: Ervin Shupe

Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 100 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 240 ft. width of ditches 3 ft. depth of ditches 21 in.

French Drain Required: _____ Linear feet

Date: 6/11/2014

Inspected by: [Signature]
Environmental Health Specialist

PERMIT NO. 20815

