

04-5-10724
HTE ATTEMPT TO REPAIR

H. ETT COUNTY HEALTH DEPAR ENT
ENVIRONMENTAL HEALTH SECTION

16714

OPERATIONS PERMIT

Name: (owner) MELZAC, STEVE & TAMMY ☐ New Installation ☒ Septic Tank
Property Location: SR# 1156 ARCHIE ST. ☒ Repairs ☒ Nitrification Line
Subdivision ANDERSON CREEK HOMES Lot # 30
Tax ID # _____ Quadrant # _____
Contractor: _____ Registration # _____

Basement with Plumbing: ☐ Garage: ☐

Water Supply: ☐ Well ☒ Public ☐ Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: ☐ Conventional ☒ Other PUMP TO CONVENTIONAL

Size of tank: Septic Tank: 1000 gallons Pump Tank: 1000 gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 200 ft. width of ditches 3 ft. depth of ditches 18-24 in.

French Drain Required: _____ Linear feet

Date: 12/13/04

Inspected by: [Signature] RS
Environmental Health Specialist

PERMIT NO. 21420

