Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section					Sheet: Property ID: Lot #: File #:				
SOIL/SITE EVALUATION Code: for ON-SITE WASTEWATER SYSTEM									
Locati Water Evalua Type o		l: Aug	Date Desi Prop	e Evaluated: /o//c gn Flow (.1949): erty Recorded: Individual Pit Industrial	Property S Well	g 🗌 Oth	er		
P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	. 1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	45 2%	6-48	G145	VERUSAP					5.2
					· · · · · · · · · · · · · · · · · · ·				
		0-48	G/M	VERNENP					5.8
_									
						· ·			
									······
Description Initial Repair System Other Factors (.1946):									

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): 5
Available Space (.1945)			Evaluated By: 6
System Type(s)	2570	2570	Others Present:
Site LTAR	. 8	. 8	