Department of Environment, Health and Natu -- esources Division of Environmental Health On-Site Wastewater Section Sheet: Property I Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: A	pplicant:		-1 1		
Address:	_	Date Evaluated:	913,1,1		
Proposed Facility: 3	360 ~	Design Flow (.19	49): 360 56	Property Size:	
Location of Site:	-	Property Recorde	ed:		
Water Supply:		ic Individual	☐ Well	☐ Spring	Other
Evaluation Method:	Auger Boring	☐ Pit		Cut	
Type of Wastewater:	Sev	age Ind	ustrial Process	☐ Mixed	

# Position			SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
\	2.5	0-48	65	vas ve jus					2.8
2		0-48	Go	mle m					2.8
		_							

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)		V	Evaluated By:
System Type(s)	CON	CC~	Others Present:
Site LTAR	, 2	4	

COMMENTS: '____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE SG-SINGLE GRAIN M- MASSIVE

IV

GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMATIC

CR-CRUMB

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

Show profile locations and other site features (dimensions, references or benchmark, and North)

