



**Harnett County**  
 108 EAST FRONT STREET  
 LILLINGTON, NC 27546  
 Phone:  
 Fax:

10/1/2019

**SUBJECT: RA2017-50041690  
 BUILDING RESIDENTIAL**

To: STAFFORD BRIAN

Here are the results of all Inspections located at **2229 MCNEILL RD:**

Inspection Type: MH FOUND/MARRIAGE WALL  
 Scheduled Date/Time:  
 Completed Date/Time:  
 Inspector: Scott Guy  
 Result:  
 Remarks:  
 Notes:

Inspection Type: ENVIR. HLTH. CONFIRMATION  
 Scheduled Date/Time: 7/7/2017  
 Completed Date/Time: 6/30/2017  
 Inspector: Unassigned  
 Result: APPROVED  
 Remarks:  
 Notes: T/S: 07/05/2017 09:38 AM KHINSON -----

Inspection Type: R MOBILE HOME FOUND./ M. WALL  
 Scheduled Date/Time: 12/4/2017  
 Completed Date/Time: 12/4/2017  
 Inspector: Unassigned  
 Result: DISAPPROVED WITH PEN  
 Remarks:  
 Notes: 1-PLUMBING NOT INSTALL 2-ELETRICAL NOT INSTALLED 3-VAPOR BARRIER NOT INSTALL JOB NOT READY

Inspection Type: ENVIR. OPERATIONS PERMIT  
 Scheduled Date/Time: 6/7/2018  
 Completed Date/Time: 6/8/2018  
 Inspector: Unassigned  
 Result: APPROVED  
 Remarks:  
 Notes: T/S: 06/08/2018 11:44 AM LLUCAS ----- T/S: 06/08/2018 11:45 AM LLUCAS -----  
 -----  
 T/S: 06/08/2018 11:45 AM LLUCAS -----





**Harnett County**  
108 EAST FRONT STREET  
LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: MH FOUND/MARRIAGE WALL

Scheduled Date/Time: 7/26/2019

Completed Date/Time: 7/26/2019

Inspector: Scott Guy

Result: DISAPPROVED

Remarks:

Notes:

1- Ductwork under home still not attached. 2- vapor barrier still not installed. 3-electrical in ground covered, this depth must be verified. Note: water service is completely covered. Water service inspection was never scheduled per the system records