Department of Environment, Health and Natur Cources
Division of Environmental Health
On-Site Wastewater Section

Applicant:

Owner:

Address:

Description

System Type(s) Site LTAR

Available Space (.1945)

Initial

System

00~

2×30 6

Repair System

18-30

Cha

Sheet:
Property ID
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Date Evaluated:

Location Water Evalua	sed Facility: on of Site: Supply: ution Method of Wastewate	Auge	Prope ☐ Public ☐ In	n Flow (.1949): rty Recorded: dividual Pit Industrial P	☐ Cut	e:	eer		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	45	0-48	6 5	and was					۶٬۹
2		048	65	gricu sar					5.4
			1450						

Other Factors (.1946):

Site Classification (.1948):5

Evaluated By: 0

Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I	S-SAND LS-LOAMY SAND SL-SANDY LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM	0.8 - 0.0	VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

MINERALOGY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

GR-GRANULAR


SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

PR-PRISMATIC

SLIGHTLY EXPANSIVE

EXPANSIVE



Harnett County GIS



