HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Laura Dixon

Phone #: 919-916-8277

Address: 100 Overby Ct Fuguay Varina NC 27526

Name of Mobile Home Park or S/D: River Pines lot 3

Name of Owner (if different): Lin Pei Chun Tic & Sung Hui Chun Tic

Address of Owner (if different): 2421 N Bell Ave Apt 103 Denton TX 76209

Property Location (State Road name and #): 1257 South River Rd

Purpose of Inspection: Man Home (16'x76')

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

AUTHORIZATION OF EXISTING SYSTEM

Signature of Environmental Health Specialist