

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS <i>P1</i>		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-8	→								
TEXTURE GROUP	.1941(A)(1)	LS									
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 2 DEPTH		8-18	→								
TEXTURE GROUP	.1941(A)(1)	SCL									
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 3 DEPTH		18-36	→								
TEXTURE GROUP	.1941(A)(1)	SC									
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH		36+	→								
TEXTURE GROUP	.1941(A)(1)	PM									
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.25	→								

1 x 5/6
18" max
4B2