

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	✓	✓	✓							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-8	0-10	0-8							
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FL									
STRUCTURE	.1941(A)(2)	CL									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		8-18									
TEXTURE GROUP	.1941(A)(1)	SC									
CONSISTENCE	.1941	FL									
STRUCTURE	.1941(A)(2)	CL									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 3 DEPTH		18-36									
TEXTURE GROUP	.1941(A)(1)	SC-CL									
CONSISTENCE	.1941	FL									
STRUCTURE	.1941(A)(2)	SPL									
MINERALOGY	.1941(A)(3)	SSP									
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.35	.4	.35							