

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-6	0-10								
TEXTURE GROUP	.1941(A)(1)	SL	SL								
CONSISTENCE	.1941	VFR									
STRUCTURE	.1941(A)(2)	CR									
MINERALOGY	.1941(A)(3)	NS/NP									
HORIZON 2 DEPTH		6"±	10"±								
TEXTURE GROUP	.1941(A)(1)	C	C								
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	SBK									
MINERALOGY	.1941(A)(3)	SS/SP									
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	24"	24"								
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.3	.3								

