

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L	L	L					
SLOPE (%)	.1940		2	2	2	2					
HORIZON 1 DEPTH			0-10								
TEXTURE GROUP	.1941(A)(1)		SL								
CONSISTENCE	.1941		PL								
STRUCTURE	.1941(A)(2)		OL								
MINERALOGY	.1941(A)(3)		NSNP								
HORIZON 2 DEPTH			10-30	ll	ll	l					
TEXTURE GROUP	.1941(A)(1)		SCL								
CONSISTENCE	.1941		PK								
STRUCTURE	.1941(A)(2)		COL								
MINERALOGY	.1941(A)(3)		NSNP								
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942		24	24	26	26					
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955		.3	.3	.5	.3					

C1428