

Applicant:

Date Evaluated: 11/24/08

Property Size:

Property Recorded:

Owner:

Address:

Proposed Facility: 3 Bedroom Home Design Flow (.1949): 360 sq ft

Location of Site:

Water Supply: ☐ Public ☐ Individual

☐ Well

[] Spring

☐ Other

Evaluation Method: ☒ Auger Boring

[] Pit

[] Cut

Type of Wastewater: ☒ Sewage

☐ Industrial Process

[] Mixed

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	CO 2	CO 2
Site LTAR	.5	.5

Other Factors (.1946): _____

Site Classification (.1948): 25

Evaluated By: _____

Others Present: _____


4x60' @ 24"
= REPAIR

LILLINGTON SERIES 5012
HAR DUE TO COBBLES

COMMENTS: _____

<u>LANDSCAPE POSITIONS</u>	<u>GROUP</u>	<u>TEXTURES</u>	<u>.1955 LTAR</u>	<u>CONSISTENCE MOIST</u>	<u>WET</u>
R-RIDGE	I	S-SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
S-SHOULDER SLOPE		LS-LOAMY SAND			
L-LINEAR SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FR-FRIABLE	SS-SLIGHTLY STICKY
FS-FOOT SLOPE		L-LOAM		FI-FIRM	S-STICKY
N-NOSE SLOPE	III	SI-SILT-	0.6 - 0.3	VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE		SIL-SILT LOAM		EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE		CL-CLAY LOAM			SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SCL-SANDY CLAY LOAM			P-PLASTIC
T-TERRACE		SICL-SILTY CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN	IV	SIC-SILTY CLAY	0.4 - 0.1		
		C-CLAY			
		SC-SANDY CLAY			
<u>STRUCTURE</u>		<u>MINERALOGY</u>			
SG-SINGLE GRAIN		SLIGHTLY EXPANSIVE			
M-MASSIVE					
CR-CRUMB		EXPANSIVE			
GR-GRANULAR					
SBK-SUBANGULAR BLOCKY					
ABK-ANGULAR BLOCKY					
PL-PLATY					
PR-PRISMATIC					

Show profile locations and other site features (dimensions, reference or benchmark, and North).



SURVEY FOR: