

LILLINGTON,NC 27546 Phone: Fax:

11/18/2019

SUBJECT: SFD1809-0029 SINGLE FAMILY DWELLING

To: GARY ROBINSON HOMES LLC

Here are the results of all Inspections located at 155 TREASURE DR:

Inspection Type: SEWER CONNECTION Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type: FINAL** Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type:	INSULATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

FINAL SFD STEMWALL**
Deen Taylor
eTRAKiT Inspection Request





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	Deen Taylor APPROVED
Notes: Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector:	10/31/2018 Deen Taylor
Result: Remarks: Notes:	APPROVED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	FOUNDATION 11/13/2018 11/13/2018 Deen Taylor DISAPPROVED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	FOUNDATION 11/14/2018 11/14/2018 Deen Taylor APPROVED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	UNDER SLAB TRADES 11/27/2018 11/27/2018 Deen Taylor APPROVED



50		t County ST FRONT STREET
Harnett c o u n t y NORTH CAROLINA	LILLING Phone: Fax:	GTON,NC 27546
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	ROUGH IN 2/6/2019 2/6/2019 Deen Taylor DISAPPROVED 1. All bottom plates in garage wing walls must have a minimum two anchor bolts, consult engineer. 2. Provide complete and in order truss packet. 3. Trusses not strapped for uplift or web raced in accordance with documents, review all. 4. Install shingles on right side ridgeOkay to side, do not insulate
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	e/Time:	ROUGH IN 2/14/2019 2/14/2019 Ken Slattum DISAPPROVED





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time:	1. Hurricane ties needed at front and rear porch bearing walls see truss documents. 2. Girder truss be for GDR needs additional uplift. 3. Truss A4 missing bracing. 4. Need 2x2 washers at portal framing.
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	
	1. Fire block around drop ceiling in closet next to fireplace. 2. Fill holes in slab for plumbing with concrete. Ok to side and insulate
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	INSULATION 3/6/2019 3/6/2019 Deen Taylor DISAPPROVED Rough in not scheduled, previous violations not corrected
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	ROUGH IN 3/11/2019 3/11/2019 Deen Taylor DISAPPROVED Dropped ceiling above closet still not fire blocked. Wall cavities must be separated from attic
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	ROUGH IN 3/15/2019 3/15/2019 Deen Taylor FAIL W/ PENALTY Drop ceiling sill not fireblocked
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	INSULATION 3/19/2019 3/19/2019 Deen Taylor CANCELLED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	ROUGH IN 3/19/2019 3/19/2019 Deen Taylor CANCELLED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks: Notes:	ROUGH IN 3/21/2019 3/21/2019 Deen Taylor APPROVED
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks:	ENVIR OPERATIONS PERMIT 5/9/2019 5/9/2019 Andrew Currin APPROVED

Notes:

Printed: Monday, November 18, 2019 9:42:10 AM





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	WATER CONNECTION
Scheduled Date/Time:	5/29/2019 Any
Completed Date/Time:	5/29/2019
Inspector:	Deen Taylor
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	5/24/2019 9:40 AM GARY ROBINSON HOMES LLC

Contact Name: GARY ROBINSON HOMES LLC Site Address: 155 TREASURE DR Phone: 9104015505 e-Mail: patsy.grhomes@gmail.com

Inspection Type:	TEMP POWER CERTIFICATION
Scheduled Date/Time:	6/4/2019 Any
Completed Date/Time:	6/4/2019
Inspector:	Deen Taylor
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	5/30/2019 10:58 AM GARY ROBINSON HOMES LLC

Contact Name: GARY ROBINSON HOMES LLC Site Address: 155 TREASURE DR Phone: 9104015505 e-Mail: patsy.grhomes@gmail.com

Inspection Type:	FOUNDATION SURVEY
Scheduled Date/Time:	9/18/2019
Completed Date/Time:	9/18/2019
Inspector:	Jennifer Brock
Result:	APPROVED
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	FINAL SFD STEMWALL**
Scheduled Date/Time:	10/24/2019
Completed Date/Time:	10/24/2019
Inspector:	Deen Taylor
Result:	DISAPPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	10/23/2019 12:52 PM GARY ROBINSON
	Contact Name: GARY ROBINSON
	Site Address: 155 TREASURE DR
	Phone: 9104015505
	e-Mail: lauren.grhomes@gmail.com
	1. Must have positive drainage on the left side and rear of house. 2. Insulation in attic must be 10 inches settled thickness, and repair weatherstripping for attic door
	1. Must have positive drainage on the left side and rear of house. 2. Insulation in attic must be 10 inches settled thickness, and repair weatherstripping for attic door
Inspection Type:	FINAL SFD STEMWALL**
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	10/29/2019 12:47 PM GARY ROBINSON
	Contact Name: GARY ROBINSON
	Site Address: 155 TREASURE DR
	Phone: 9104015505

e-Mail: Adamw.grhomes@gmail.com

