

SFD 1809-0029
 South Creek S/D
 Lot 12

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner: 401 SWV Applicant: Gary Robinson Home, LLC
 Address: 155 Treasure Dr. Date Evaluated: 10/04/2018
 Proposed Facility: 432 SFD Design Flow (.1949): 480 GPD Property Size: 0.52 AC
 Location of Site: Water Supply: Public Individual Well Spring Other
 Evaluation Method: Auger Boring Pit Cut
 Type of Wastewater: Sewage Industrial Process Mixed

P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	L 4-6%	0-12	CL LS	VR WSNP					PS
		12-48	BR SL	FR SSSC		48			0.4
2	L 4-6%	0-12	CL LS	VR WSNP					
		12-46	BR SL	FR SSSC					PS
		46+	Parent mat.	—		46			0.4
3	L 4-6%	0-12	CL LS	VR WSNP					
		12-44	BR SL	FR SSSC					PS
		44+	Parent mat.	—		44			0.4

Description	Initial System	Repair System	Other Factors (.1946):
Available Space (.1945)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	Site Classification (.1948): Provisionally Suitable
System Type(s)	25% 40	25% 40	Evaluated By: Andrew Curran, DEHS
Site LTAR	0.4	0.4	Others Present: