Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

SED1811-0011

water	. Supply:		t: Wood Con Date Design Propo Public In Sewage	Evaluated: 1 2. gn Flow (.1949): 3 erty Recorded: ndividual Pit Industrial	Well ☐ Sprin				
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		10.60				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2,3	L24%	0-14	GL SL	VA NSN					P5
		14-48	3N SLL	TN 4350		48			P5 6.4
							ľ		

Description	Initial	Repair System	Other Factors (.1946):
	System	/ /	Site Classification (.1948): Provisionally Svitable
Available Space (.1945)			Evaluated By:
System Type(s)	25% Red	25% red	Others Present: Andrew Currin, 1845
Site LTAR	0.4	014	
	, ,	7,4	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET	
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY	
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC	
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3			

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY
PD. PDISMATIC

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

IV

EXPANSIVE

C-CLAY SC-SANDY CLAY

