

Joe E Godwin Sr., P.E., P.L.S.

Fleet Temple, P.E.

Jason E Godwin, P.L.S.

# ENOCH ENGINEERS, P.A.

1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION FIELD REPORT

### PROJECT

CLIENT: Cumberland Homes	DATE: 5.7.19
PROJECT: South Creek s/d	CONTRACTOR: c/o dennis norris
ADDRESS:	TECHNICIAN: BH
LOT #: 25	

### TEST SUMMARY

Performed NDT on pad at site noted above using target density of 100 PCF. soils confirmed a compaction greater than or equal to 95%.

### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %
NDT	1	100+	105.9	103.8	2.0

### RETURN VISIT REQUIRED?

YES

NO

TECHNICIAN:

Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.