A A TAKLA ENGINEERING, PLLC

Consulting. Design. Efficiency.

ANDY A. TAKLA, EI

919-423-0470 ANDYTAKLA@TAKLAENGR.COM Cert. #A-29014 ATEF A. TAKLA, PE 919-358-1758 ATEFTAKLA@TAKLAENGR.COM Lic. #14578

ALFRED A. TAKLA, EI 919-332-7903 ALFREDTAKLA@TAKLAENGR.COM Cert. #A-20939

NC Firm License No. P-1446 PO Box 71298 Durham NC 27722

	FIELD REPORT
Date: Project:	4 30 19 Agranda McDaugald RD 1:115
Location:	LILINATON, HC
Company:	Value Build
Care of:	Paul Mcne. 1 4 30 19
Así	PEQUESTED, A. TAKIA prepared This
repu	
A) (sarage's Dooi2 Rooting (was missing)
was observer and found adequate	
per plan meet cope w/ 2000 psf	
-	searing capacity
	3 1 0
	O.K TO DOWN-
-	

Limitations of Inspection Services provided are in accordance with the standard of practice for structural engineering and within the limits imposed by scope, schedule and budget. The determinations contained in this report are based on conditions observed at the time of the evaluation. No quarantees or warranties, expressed or implied, under this Agreement or otherwise, shall be construed in connection with services provided. Sequencing, and means and methods of construction are considered beyond the scope of this report.